

SURVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of

P.A. Of 1990 On 12/9 199 94

For corners in
MENOMINEE
(County)

APR 11 1995

Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

Located In:

Corner Code #

- | | | |
|------------------------------------|---------------------------|-------------|
| 1. Public Land Survey | T <u>33N</u> R <u>27W</u> | <u>C-09</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

RECEIVED FOR RECORD
DEC 12 AM 8:59
Chairman
ARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE MI 49858

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

William Lenca

May 20

94

I, _____, in a field survey on _____, 19 _____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1852: Original Survey by John Mullett - B.T.'s - Hemlock, 12" - N14°E - 23 lks; Birch, 16" - S64°W - 20 lks. All original evidence for this corner has been destroyed by county road improvements.

1981: L.C.R.C. No. 316 by George B. Wilson, RLS No. 17607, states that he dug a hole 10' x 10' x 3' deep with County Equipment. He found a flat stone with "x" chisled on top. He set a W-1-B Berntsen Monument - TIES - Deep 1 - 45' SW; Deep 1 - 45' NW.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found the W-1-B Berntsen Monument, mentioned in part "A", in the centerline of an East - West County Road and in line with an old fence line running North from this location. This corner has been used by local surveyors for several years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

5/8" x 24" Iron Rod/2" dia. Alum. cap - WITNESS MARKER	North	33.00 feet
5/8" x 24" Iron Rod/2" dia. Alum. cap - WITNESS MARKER	N64°E	109.80 feet
5/8" x 24" Iron Rod/2" dia. Alum. cap - WITNESS MARKER	S70°E	109.94 feet
1/2" dia. Iron Pin in 4" square concrete monument	S05°E	32.94 feet
Survey Sign Post	North	33.2 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca

Date

Sep. 26, 1994

Surveyor's Michigan License No. 26461