

SURVEY & REMONUMENTATION

For corners in APR 11 1995

MENOMINEE

(County)

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Located In:

Corner Code #

- | | | |
|------------------------------------|---------------------------|-------------|
| 1. Public Land Survey | T <u>33N</u> R <u>27W</u> | <u>E-10</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

William Lenca

Jun 29

94

I, _____, in a field survey on _____, 19 _____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1852: Original Survey by John Mullett - B.T.'s - Tamarack, 10"- N33°E - 10 lks; Tamarack, 10" - S22°W - 10 lks - All original evidence for this corner has been destroyed by logging activities.

1893: A.L. Hillis, a Surveyor from Marinette, Wisconsin, set a 1-1/2" square iron bar 40" long from original evidence. His field book is on record in the City of Marinette Engineers Office.

1975: L.C.R.C. No. 110 by George B. Wilson, RLS No. 17607, states that he found a 1-1/4" square iron bar as described above - B.T.'s - 7" Tam - 148° Azm - 10.3'; 7" Y. Birch - 164° Azm - 15.2'; 7" W. Birch - 284° Azm - 16.4'; 6" Ash - 360° Azm - 9.1'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a 1-1/2" square iron bar 40" long as described above in location indicated by retracement of the East Line of Section 29, T33N-R27W. We also recovered the stumps of 3 of the B.T.'s mentioned in L.C.R.C. No. 110. The 7" W. Birch was gone. Since A.L. Hillis set the 1-1/2" square iron bar from original evidence, we accepted his monument as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2-1/2" dia. Alum. Pipe 30" long/3-1/4" dia. Alum. cap stamped for corner location:

6" dia. Elm	N42°E	36.68 feet	Scr. NBT
6" dia. White Ash	S79°E	20.88 feet	Scr. NBT
3" dia. White Ash	S46°W	7.61 feet	Scr. NBT
6" dia. White Ash	N68°W	26.24 feet	Scr. NBT
Survey Sign Post	North	1.0 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca

Date _____

Sep. 26, 1994

Surveyor's Michigan License No. _____

26461

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of

P.A. Of 1990 On 12/9 199 94

McDowell RLS

ACTING Chairman

BARBARA MORRISON

REGISTER OF DEEDS

ENOMINEE MI 19958

AGE # 118 BK-4

DEC 12 AM 8:59

RECEIVED FOR RECORD

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

