Approved by Menominee County Land Survey Remonumentation Peer Group Under Act 345 Of 1990 On 199 \_\_\_ 199*.25* 

P.A. Of 1990 On

	Filing	Requirem	ent of Act 74,	Mich D & 10	70	THE	Chairman	ELS
For corners in	· ····· <b>g</b>	- 1			, ,		Ondithion	
MENOMINEE	Located In:	O.m 1	n		•	g	<u>ک</u> چ	
(County)	Localed III.	Corner (	J008#			23	第 5	KEOEIVED FOR
						1,000 1,000		$\Xi$
1. Public Land Survey	T33N_R_2	7W	M-6			-= - 15 15	200	<u> </u>
•	<u>TR_</u> _	<del>-</del> -		İ		(*********	: 7 -1	**** ****
	ŢR_			1		(*147) 1111	===	22 22
2. Property Controlling	TR_ S TR_			İ		- 10 m ± ±		ar fra
in Section	S TR_			1		286	3 7 3	
3. Miscellaneous	S T R		<del></del>	1			£ 1/20	
Property in Sec.	S TR			Ī				
				L	Regist	er of Deed	s Stamp &	File Numbe
4 1 -4 M - B								
4. Lot No, Reco	ded Plat				АВО	DE	FGH	IJKI
3. Filvate Claims						<u> </u>	ΠÏ	
(SAME AS CORNER A	06 T33N-R26W)				2 - 6-	<b>-</b> \$	4	<del>┦╼</del> ┆┷┼╌┆
	•	Aug. 04. 19 95 do hereby state that under corner points mentioned in fines 1 and 2 above were in ulired in the current manual of survey instructions of the do Management or by a decree of a Court of Law and/or ove were in conformance with the rules of the Michigan rt of Law; established, re-established, monumented, town and range, may be recorded  3 4 7 8 9 10 11 12 31 38 9 10 11 12 31 32 33 34 35 36						
I, William Lenca	, in a field survey on	Aug. 04, 1	9 95 do hereby :	tate that under	4	b	910	- 111
requirements of P.A. 74, Michiga conformance with regulations and	In P.A. of 1970, the comer   I fulse therefore as required i	points mention in the current re	ed in lines 1 and 2	above were in	5			
United States Department of the	Interior, Bureau of Land Man	agement or by	a decree of a Court	of Law and for	6 -18-	_171	[	1 1
that the corner points mentioned	i in lines 3, 4 and 5 above we	ere in conforma	ince with the rules (	of the Michigan	1 1 1		Ľ ľ	
recovered, found as expressed be		_aw; establish	ea, re-establishea,	monumented,				
•					1 1			
	ers, all in the same town a	and range, ma	ay be recorded		·     1			-
on this certificate.					10 30	—2 <del>9</del> ——2	827	26 - 2
					11	<del></del>	<del>   -</del>	<del>   -  </del>
					12 31	3/23	334	353
		•			13			
A. Description of original mo	nument and accessories	and/or subse	equent restoratio	n:				
evidence has bee 1984: L.C.R.C. No. 59	by James H. Mullett - I en destroyed by county re 6, recorded by George E intersection. TIES: De	oad improve 3. Wilson, Ri	ements. LS No. 17607 s	tates that a De	en-1 magne	t was set		<del>-</del>
B - B								
B. Description of corner evid	lence found and/or meth	od applied in	restoring or rees	tablishing corn	er:			
In our 1995 Remonument running North - South and several years, and is accep	d East - West. This mor	nument fits :	with existing lin	es of occupation	on has been	line of C	ounty Road ocal surve	ds yors for
•								
C. Description of monument f Set 5/8" x 24" Iron Rod/3-	or corner and accessorie	s established	d to perpetuate to mer location in i	cating the posit	tion of the co x:	orner:	SINIE OF	NICHIEN
8" dia. White Pine		N680E	104.72 feet	Scr. NBT		# #	! LEN	
6" dia. Tamarack		S520E	79.49 feet	Scr. NBT		# E	SURVI	YOR *
13" dia. White Ash		S610W	67.52 feet	Scr. NBT		8 =	No.	
9" dia White Ash		N430W	65.85 feet	Scr. NBT		Ø.	?:` <b>``</b>	
Metal Survey Sign Pos	į.	S42°E	55.3 feet			*	ANTRED II	NO SURPORT
NOTE: All bearings are natree.	agnetic bearings. All d	listances are	measured with	a steel tape. D	istances to	trees are t	o nail in s	ide of
109100	1 Jan.			Nov	. 27, 1995			•
Signed by	of origo			Date				
Surveyor's Michigan License N	lo. 26461							