SURVEY & REMONUMENTATION

FEB 1 1 1998

B 1 1 1998				Approved by Menominee County Land Survey Remonuncentation Feer Group Under Act 245 Of P.A. Of 1990 Og			
	LAND CORNER RECORDATION	ON CERTIFICA	TE	Mel	Challengen	RLS	
ECTION	Filing Requirement of Act 74,	Mich. P.A. 197	0	, e	S CO		
MENOMINEESURVEX.					(") ~~~	(")	
REMONUMENTA				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		55 55 55 55 55 55 55 55 55 55 55 55 55	
				715 1120*	6 5	65	
1. Public Land Survey	T <u>B4N R 27W H-11</u> T R	ŀ		412 412	C mo	;;	
2. Property Controlling S	T R		Registe	ar of Dee	BKS de Stamp	\$ File N	umbi
A Stable Described Dist							
4. Lot No, Recorded Plat 5. Private Claims		rdid-raw-a	A B C	DE	F G H	1 J	K I
C, I IIVato Oldillo			2 0				
		-	3	_ _ _	<u> </u>		-ļĪ
L William Lonca , in a field :	survey on May 13, 19 97 do hereby	state that under	4 - 7 -	- - -	- 910		- -
requirements of P.A. 74, Michigan P.A. of 1970 conformance with regulations and rules therefore	O, the corner points mentioned in lines 1 and e as required in the current manual of survey it	2 above were in structions of the	5		1 1		
United States Department of the Interior, Bureau that the corner points mentioned in lines 3, 4 ar	u of Land Management or by a decree of a Cou	art of Law and for	6 -18-	-17	16	,- 4-	- - 1
Board of Land Surveyors or by a Decree of			7		1-1-1	_	+-
recovered, found as expressed below:			8 19	20	-21	:23 I	- 2
NOTE: Not more than 2 corners, all in the	same town and range, may be recorded		9		- [-
on this certificate.			10 30-	-29- -	2827	26-	-1-2
			11		1		
•			12 31	72	3334	33-	
A. Description of original monument and	accessories and/or subsequent restorat	ion:	13				
evidence for this corner has be 1991; L.C.R.C. No. 911 by William north and west and in line w	Muliett - B.T.'s - Sugar, 8" - N03°E - been destroyed by county road improven Lenca, RLS No. 26461, states "Four ith aucient fenceline to the east." TIE 46.61'; W. Ash, 8" - N12°W - 73.70'.	ements. nd 5/8" dia, iron i	n line witl	a county	road cent	crlines	
B. Description of corner evidence found a We recovered a 5/8 inch x 21 inch Iro ancient fence running east. We also f local surveyors for several years, and it	ound the B.T.'s as described in L.C.R.	unty roads runnin C. No. 911 (see p	ig north an part A). Ti	his corne	r has beer		
					ELETATE O	manazação Historia	
					∗ W⊪	NCA	*
C. Description of monument for corner and	d accessories established to perpetuate	locating the positi	on of the co	# ∰ ± Enemo		AND	*
Set 2" dia. Aluminum Pipe/3-1/4" dia.				El,	1	No. (645)	: 5
DOLZ CHE PHINIMINE FINAS-1/4 UIA.	. zamin sap aminpon tor corner rocatio	•••		É	S		s/
	cap marked "WITNESS MARKER"		.45 fcci		30,500	Π.,	-
5/8" x 24" Iron Rod/2" dia. Alum.	<u> </u>		CE E4				
10" dia. Apple			.65 feet	Con NT	ידכ		
10" dia. Apple 10" dia. W. Ash		N13°W 73	74 feet	Scr. N.			
10" dia. Apple		N13°W 73 S87°E 107	•	Scr. N. Scr. N.			
10" dia. Apple 10" dia. W. Ash 7" dia. Maple		N13°W 73 S87°E 107 East 27	.74 feet .20 feet .05 feet	Scr. N	BT	side of tre	œ.
10" dia. Apple 10" dia. W. Aslı 7" dia. Maple Metal Survey Sign Post		N13 ⁰ W 73 S87 ^o E 107 East 27 In steel tape. Dis	.74 feet .20 feet .05 feet	Scr. N	BT	side of tre	ec.