

FEB 11 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Pair Group Under Act 345 Of
P.A. Of 1990 On 12/18, 1997
McDermis RLS
Chairman

For corners in
MENOMINEE

Located In:

Corner Code #

(County)

1. Public Land Survey

T34N R 27W E-7/8
(006)

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William Lenca, in a field survey on Nov. 26, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	10		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by James H. Mullett - B.T.'s - Hemlock, 14" - S14°E - 29 lks.; Cedar, 14" - S26°W - 09 lks. All original evidence for this corner has been destroyed by river erosion and ice shoves.
- 1926: Plat of Schuette Summer Resort No. 1 by A.L. Hillis shows Plat Monuments at points where the East line of Section 20, T34N - R27W enters and crosses the plat. These monuments have been destroyed by road & driveway construction.
- 1981: Plat of Robert's Subdivision by George B. Wilson, RLS No. 17607, details how these points were re-monumented, and indicates that concrete monuments were placed at the point where the East Line of Section 20 crosses the Southerly Line of Shore Drive as platted in the Plat of Schuette Summer Resort No. 1.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a concrete monument shown on the plat of ROBERT'S SUBDIVISION as being 8.58 feet S54°20'W from the East Line of Section 20. We then re-established the position of the monument on line between Sections 20 & 21 and projected this line North to the Menominee River, and accepted this location as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum cap stamped for corner location:

4" Square Plat Monument	N62°E	33.15 feet
N.W. Corner of House Foundation	S37°E	65.05 feet
20" dia. Oak	S39°W	14.80 feet
Metal Survey Sign Post	N24°W	4.8 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Dec. 15, 1997

