

REMONUMENTATION

FEB 11 1998

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On 10/31, 1997
McLain RLS
Chairman

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T34N R 27W

B/C-11

T R

009

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, William Lenca, in a field survey on Oct. 22, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| 1 | | | | | | | | | | | | | |
| 2 | | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | | |
| 4 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 5 | | | | | | | | | | | | | |
| 6 | | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | |
| 7 | | | | | | | | | | | | | |
| 8 | | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | |
| 9 | | | | | | | | | | | | | |
| 10 | | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | |
| 11 | | | | | | | | | | | | | |
| 12 | | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by James H. Mullett - B.T.'s - W. Pine, 12" - N44°E - 12lks.; W. Pine, 12" - S44°W - 12 lks. All original evidence for this corner has been destroyed by shore erosion and ice shoves.
- 1926: Plat of Wallace Summer Resort by A.L. Hillis, shows a concrete monument set on the shore of the Menominee River 503.8' West of the NE Corner of Section 31. Another concrete monument is shown 262.83' West of the NE Corner.
- 1961: Rober Olsen survey shows an existing concrete monument at the NE Corner of Section 31 and an existing concrete monument 278.2' (recorded as 262.83') West. His survey indicates that the Meander Corner Monument has been destroyed.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 4 inch square concrete monument with a 1 inch diameter iron rod in the center at the Northeast Corner of Section 31 and another identical monument 278.2 feet West of this corner. We projected the line between these monuments West to a point 503.8 feet West of the Northeast Corner of Section 31. It appears that any monument placed in this location would have been destroyed by shore erosion. Using the above projection, we re-set this corner on top of the high bank of the Menominee River, and accepted it as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe 3-1/4" dia. Alum cap stamped for corner location:

| | | | |
|------------------------|-------|------------|----------|
| 8" dia. White Pine | N06°E | 29.89 feet | Scr. NBT |
| 18" dia. Jack Pine | East | 21.08 feet | Scr. NBT |
| 8" dia. White Pine | S58°W | 8.38 feet | Scr. NBT |
| Metal Survey Sign Post | West | 0.9 feet | |
| Edge of River Bank | West | 12.0 feet | |
| Menominee River | West | 30.0 feet | |

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Oct. 24, 1997

