## SURVEY & REMONUMENTATION

JAN 09 2001

Approved by Mei	nominee	County
Land Survey Re	monume	entation
Peer Group Un	der Act 3	345 cf
Peer Group Un PA. Of 1990 On	7/13	. 20⊈
	4.44	· 707

SECTION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in MENOMINEE Located in: Corner Code # (County) E-10 1. Public Land Survey RECEIVED FOR RECORD T 10:16:09 R 13 DEC 2000 2. Property Controlling in Section R 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. , Recorded Plat 5. Private Claims 1 2 3 I. William Lenca , 19<sup>00</sup> May 30 in a field survey on do hereby state that under 4 requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in 5 conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or 6 that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 8 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 10 11 A. Description of original monument and accessories and/or subsequent restoration: Original Survey by James H. Mullett - B.T.'s - Hemlock, 10" - S50°W - 04 lks.; Hemlock, 8" - N38°E - 09 lks. All original 1848: evidence for this corner has been destroyed by logging activities. 1956: L.C.R.C. No. 36, Volume 2, by Billy D. Buckler, RLS, states that a 1" pipe with 4" brass cap was set in place of old Cedar Stake at old fence corner 40.00 chains South of Section Corner in Road int. Fence line North & West. B.T.'s: 6" Soft Maple - East - 40 lks; 6" Soft Maple - S10°W - 56 lks. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We found a 1 inch diameter iron pipe with a 4 inch diameter brass cap at an ancient fence corner, along with the 2 B.T.'s as described in LCRC No. 36, Vol. 2 (see part A). This corner has been accepted and used for at least 44 years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

Accepted Existing 1" dia. Iron Pipe/4" Brass Cap stamped for corner location.

N49 <sup>0</sup> E	30.56 feet	Scr. NBT
S270E	41.58 feet	Scr. NBT
S41°W	23.34 feet	Scr. NBT
N29 <sup>0</sup> W	29.83 feet	Scr. NBT
West	1.6 feet	
	S27°E S41°W N29°W	S27°E 41.58 feet S41°W 23.34 feet N29°W 29.83 feet



NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by D. Delain Jane	Date	June 30, 2000
Surveyor's Michigan License No. 26461		