

APR 06 1999

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of

P.A. Of 1990 On 12/30 1998

Mr. DAVIS RLS
Chairman

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 35 N R 27 W

C-07

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, William Lenca, in a field survey on Mar. 12, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1848: Original Survey by James H. Mullett - B.T.'s - Spruce, 8" - N12°E - 14 lks.; Spruce, 10" - S30°E - 22 lks. All original evidence for this corner has been destroyed by logging activities.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found an old squared wood post shown to us by Nick Thoney a long time area resident. He stated his dad showed him this corner 40 years ago. This corner fits well with corners 1 mile North, South, and East, and with a GLO Terrain call to a swamp edge 3.5 chains West. We accepted the position of the old squared wood post as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 4' Alum. Rod/3-1/4" dia. Alum. cap stamped for corner location:

| | | | |
|------------------------|-------|------------|----------|
| 9" dia. Cedar | N89°E | 20.76 feet | Scr. NBT |
| 10" dia. Cedar | S08°E | 55.98 feet | Scr. NBT |
| 16" dia. Cedar | S65°W | 50.87 feet | Scr. NBT |
| 6" dia. Cedar | N40°W | 51.61 feet | Scr. NBT |
| Metal Survey Sign Post | West | 1.3 feet | |

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca

Date Mar. 18, 1998

Surveyor's Michigan License No. 26461

RECEIVED FOR RECORD
99 JAN -6 AM 8:54
PAGE # 712 BKS
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE, MI 49856

Register of Deeds Stamp & File Number

| | | | | | | | | | | | | |
|----|----|---|----|---|----|---|----|---|----|---|----|---|
| A | B | C | D | E | F | G | H | I | J | K | L | M |
| 1 | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 5 | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | |
| 7 | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | |
| 9 | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | |
| 11 | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | |
| 13 | | | | | | | | | | | | |

