MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 35 NR 28 W

			Metromines	COUNTY
DESCRIPTION	OF CORNER	Section Cor	ner common to Sec.	18 4-5-8-9
DESCRIPTION	OF CORNER	MONUMENT_	l" pipe with 4" bre	ass cap
WITNESSES T	O CORNER _	7" Red Oak	N 85° W Marked "S5" NBT"	45 links
		10 Red Oak	s 53° w	45 links
		8" Red Oak	Marked #S8 NBT# 5 S 22 E	31 links
			Marked "S9 NBT"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner from two Y. Pine B.T.s!

Found notch on stump bearing S 42° E 93 links and burned stump bottom N 29° W 56 links.

Position checks with corners in all four directions.

No evidence of use.

Corner found by Forestry Division Survey Crew while making a re-survey of this township.

SURVEYORS SEAL