

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Menominee
(County)

Located In:

Corner Code ~~##~~

- | | | | | | |
|------------------------------------|---|------------|---|------------|------------------|
| 1. Public Land Survey | T | <u>35N</u> | R | <u>28W</u> | <u>B-3, C-2.</u> |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous | S | | T | R | |
| Property in Sec. | S | | T | R | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, David Babbitt, in a field survey on 9/18, 1986, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- B-3. South 1/4 corner of Section 6. Wood post. Maple 10, N58W, 55 Lks.
W.Birch 8, S33E, 30 Lks.
- C-2. East 1/4 corner of Section 6. Wood post. W.Pine 20", S27W, 382 Lks.
Other timber distant.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- B-3. Set by single proportion to the GLO record between the SE and SW section corners of Section 6.
- C-2. Found old sq. cedar post remains. Not of record but it is nearly in the proportionate position. Set DNR monument in place of post.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | |
|---------------------------------|---------------------------|
| B-3. 8" W.Oak, S68E, 2.0' | C-2. DNR Monument. |
| 11" W.Pine, N8W, 41.2' | 3" Oak, N8W, 8.85' |
| 4" W.Oak, N32W, 18.15' | 4" Bl.Cherry, S80E, 12.1' |
| 5" leaning W.Pine, S10W, 15.65' | 5" Oak, S31E, 18.7' |
| | 6" Oak, S13W, 23.0' |

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by

David B. Babbitt

Date

1-27-87

Surveyor's Michigan License No.

21558