

JAN 09 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. Of 1990 On 7/13, 2000
MLL DAVID RLS
ChairmanFor corners in
MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 35N R 26W

E-01

T R T R T R 2. Property Controlling
in SectionS T R S T R 3. Miscellaneous
Property in Sec.S T R S T R 4. Lot No. , Recorded Plat

5. Private Claims

SAME AS CORNER E-13 T36N-R26W

I, William Lenca, in a field survey on May 25, 19 00 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by James H. Mullett - B.T.'s - Beech, 6" - N73°E - 27 lks.; Sugar, 12" - N33°W - 17 lks. All original evidence for this corner has been destroyed by county road improvements.
- 1989: Certified Survey No. 656 by William Lenca, RLS No. 26461 shows this corner as it relates to other corners in the NE1/4 of Section 5, T35N-R26W.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a Railroad Spike in the centerline of County Road No. 358 (East - West) and in line with the centerline of a County Road running North. This position matches measurements shown in Certified Survey No. 656, fits well with existing lines of occupation, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

5/8" x 24" Iron Rod/plastic Ident. cap

N56°E

56.39 feet

1.0' N of Tel. Box

5/8" x 24" Iron Rod/plastic Ident. cap

S57°E

54.96 feet

1.0' S. of Tel. Box

4" dia. Cedar

S12°W

30.05 feet

Scr. NBT

5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"

N51°W

62.00 feet

1.0' E. of Power Pole

Metal Survey Sign Post

South

26.4 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William LencaDate Aug. 8, 2000Surveyor's Michigan License No. 26461

Book 6 Page 147

RECEIVED FOR RECORD

13 DEC 2000 10:16:09 A

BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE, MI 49858

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

