LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	İ
1. PUBLIC LAND SURVEY	. T N. R E. W.		
2. PROPERTY CONTROLL- 22	,т. <u>36 ^{N.} R. 27 ^{E.} </u>	1, 3, 7, 10	
3. MISCELLANEOUS PROPERTY IN SECTION			
4. LOT NO , RECO	RDED PLAT		
5. PRIVATE CLAIMS	.		REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in field survey on September restored as expressed below an of survey instructions of the Ur court of law. Furthermore,	lines 1 and 2 above (iden 3 1980, established d in conformance with regulated States Department of that the corner points mound, recovered, restored, e	tified with circles on index l, re-established, monumente lations and rules therefore a the Interior, Bureau of Land entioned in lines 3, 4 and 5 stablished or re-established	P.A. 74, Michigan P.A. of 1970, code diagram – over) were, in a ed, re-monumented, recovered or s required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in contra or, by a Decree of a Court of
A. Description of original monument and accessories and/or subsequent restoration: W. 1/16 on the North Section line - Sec. 22; not previously established.			
N. 1/16 - corner on the West section line - Sec. 22; not previously established.			
N. 1/16 - corner on the East section line - Sec. 22; not previously established.			
S. 1/16 - corner on the West section line - Sec. 22; not previously established.			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Set M.P.O.L. between the N & corner and the N.W. section corner of Sec. 22.			
Set M.P.O.L. between th	e W % corner and the	W.W. section corner	of Sec. 22.
Set M.P.O.L. between th	e E % corner and the	W.E. section corner	of Sec. 22.
Set M.P.O.L. between th	e W % corner and the	S.W. section corner	of Sec. 22.
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: - 1" pipe, h" aluminum cap. 9" Cedar - 549°E - 5.8°; 9" (Twin) Cedar - 868°W - 8.4°; 10" Cedar - N45°W - 14.9°; 6" Cedar - North - 36.5°.			
5" Cedar - S29 ⁰ E - 18. W89 ⁰ W - 6.0'.	3°; 9" Cedar - W13 ⁰ E	- 2.8°; 4" B. Ash -	819 ⁰ W - 11.1'; 6" Cedar -
6" Cedar - M27°W - 4.5 S18°W - 13.8'.	'; ^{h"} Cedar - E26°E	- 9.5; 5" Cedar - 84	6°E - 10.2'; 5" Cedar -
4" Cedar - S12°W - 6.5 N51°W - 4.15'. SIGNED BY		- 9.4°; 7° Cedar - 114	
SURVEYOR'S MICHIGAN REGI	STRATION NO		(SEAL)
FOR STATE AND UNITED STA	TES AGENCIES:		
SIGNED BY	CHUEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY	Lawil B. Ball MICHIGAN REGISTERED LAN	DATE DATE	1-26-81
			(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

Form No. MLM735

DOUBLE DAY 8HOT & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS