

OCT 27 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of

P.A. Of 1990 On 10/11/99, 1999

For corners in

MENOMINEE
(County)

Located in:

Corner Code #

1. Public Land Survey T36N R 28W J-11
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William Lenca, in a field survey on June, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1852: Original Survey by Francis Coleman - B.T.'s - Tamarack, 4" - N44°E - 19 lks; Tamarack, 4" - S22°W - 07 lks. All original evidence for this corner has been destroyed by years of decay.
- 1999: Plat of Survey by Robert Goodreau, RLS No. 43053, shows this corner with the following ties: 5" Spruce - S01°W - 78.70'; 12" Spruce - S23°E - 64.00'; 10" Apple - S77°E - 89.32'; Pipe 4" high - S84°W - 193.03'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 5/8 inch diameter iron rod set on line and midway between the NE Corner and the NW Corner of Section 35, T36N-R28W. The corner falls on the East Border of a Marsh as called for in the GLO Notes, and is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" dia. x 4' long aluminum rod/3-1/4" dia. Alum. cap stamped for corner.

12" dia. Spruce	S23°E	62.74 feet	Scr. NBT
9" dia. Balsam	S36°W	172.67 feet	Scr. NBT
12" dia. Twin Birch	S88°E	104.76 feet	Scr. NBT
Metal Survey Sign Post	West	0.93 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Sep. 15, 1999

RECEIVED FOR RECORD
99 OCT 15 PM 1:41
PAGE # 12 OF 6
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE, MI 49858

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

