Approved by Menominee County Land Sprvey Remonumentation Peer Group Under Act 345 Of

Control of the second				P.A. Of 1990 On	/3U 1995
				Me L	MANS RES
For corners in	LAND C Filing F	ORNER RECORDAT Requirement of Act 74	ION CERTIFICATI I, Mich. P.A. 1970	E Chair	man
MENOMINEE (County)	Located in:	Corner Code #		PAGE # BARB/ REGIS MENON	RECEIVI
1. Public Land Survey	37N_R27W TR TR	<u>A-13</u>		ARA MOR STER OF D WINEE, HI	- En Fox
2. Property Controlling in Section 3. Miscellaneous Property in Sec.	TR S TR S TR S TR			Register of Deeds	8: 5 <b>5</b>
4 Let No Descrite	l mi		<u> </u>		Starting of the rediffic
4. Lot No, Recorded 5. Private Claims	ı Plat			ABCDEF	GHIJK
(SAME AS CORNERS A-01,				554-	32
requirements of P.A. 74, Michigan P. conformance with regulations and rules United States Department of the Interict that the corner points mentioned in In Board of Land Surveyors or by a D recovered, found as expressed below:	A. of 1970, the corner poil therefore as required in the tr, Bureau of Land Manage es 3, 4 and 5 above were in	nts mentioned in lines 1 and he current manual of survey it ement or by a decree of a Col	2 above were in astructions of the surt of Law and /or 6	-19 20 21	10 11 22 23 2
NOTE: Not more than 2 corners, on this certificate.	all in the same town and	range, may be recorded	9 	-30 -29 -28 - -31 -32 -33 -	27 - 26 - 2 -34 - 35 - 3
A. Description of original monume	ent and accessories an	d/or subsequent restorati	i 🏇		
evidence for this corne 1976: L.C.R.C. No. 131 by E line tree noted as W. p L.T. STP. and an 18" as a sight tree on the o record calls to hill, sw. Oak, 11" - N52°W - 7.	er has been destroyed? David B. Babbitt RLS: sine 40 inches in diam +/- W.P. stub with a variginal gov't, survey, amp edges, and stream .8'; Oak, 11" - S24°E	No. 21558 states, "Set a n. at 69.65 on the east his very definite blase and 2 This stub is 482 ft. nort ns as recorded in G.L.O - 16.6'; W. Ash, 5" - N2	t record distance not ne of Sec. 1 - T36N - " or more of over gro th of the twp. cor. T. . notes." Set 1" pipe 20°E - 19.0'.	rth from the stump of R28W and in line to be to have the position of this control of this cont	of a white pine between said we been marked corner as set fits
2224,62000000000000000000000000000000000			-		
We found a 1 inch diameter iro location as indicated in Land C Fence Corner Post. The fence I corner was re-established based of the position of the original co	orner Recordation Cer Runs East and West fron original evidence,	rtificate Number 131. ' om this location and ap	The corner falls 16 for pears to be only abou	eet South and 2 feet ut 20 to 30 years old	t West of an old  1. Since the
C. Description of monument for con	rner and accessories es	stablished to perpetuate.I	ocating the position of	f the corner: \text{\text{diff}}	TO BIGGIS
Accepted existing 1" dia. Iron F	ipe/4" Aluminum çap	(DNR monument) stan	nped for corner:	*	William + 1
6" dia. Maple 12" dia. Oak 4" dia. Maple 12" dia. Oak Metal Survey Sign Post	N26°E 10.75 ft S24°E 17.23 ft S50°W 20.00 ft N52°W 8.17 ft East 1.1 fee	Ex. B.T.  Ex. B.T.  Ex. B.T.		* * * * * * * * * * * * * * * * * * *	SURVEYOR No. 26651
NOTE: All bearings are magne	tic bearings. All dista	ances are measured with	steel tape. Distance	es to trees are to nai	il in side of tree.
Signed by William &	Ped 11		Date Dec. 28,	1998	
Surveyor's Michigan License No			Date		