

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>37</u> N. S., R. <u>27</u> E. W.	C-12, C-13
2. PROPERTY CONTROLLING IN SECTION_____	T. _____ N. S., R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, David B. Babbitt do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on April 22 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- C-12 West $\frac{1}{4}$ corner - Section 32; Wood Post, W. Pine 12 - N16°W - 49 lks.; Cedar 14 - S75°E - 64 lks.
- C-13 S.W. Section corner - Section 32; Wood Post, Hem. 12 - N70°W - 14 lks.; Hem. 13 - N55°E - 20 lks.; Lynn 12 - S71°E - 40 lks.; Y. Birch 12 - S35°W - 38 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- C-12 Found remains of both O.B.T. stumps both show axe marks but no scribing, they have been badly burned. Bearings and distances check very well. In addition, there is a W.P. stp. N.E. with a small blaze facing the corner position.
- C-13 Set by prop. mea. and on line between the S.E. section corner of Sec. 32 and the S. $\frac{1}{4}$ corner of Sec. 31. Mea. to corners north and south are good and swamp calls fit well.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- C-12 1" pipe, 4" aluminum cap; 6" Cedar - S6°W - 41.1'; 7" Cedar - S77°E - 43.5'; 11" W. Spruce - N38°W - 41.15'; 6" Twin H. Maple - N30°E - 25.8'.
- C-13 1" pipe, 4" aluminum cap; 4" Black Cherry - N87°W - 21.55'; 4" Balsam Fir - N72°E - 34.30'; 9" Cedar - S37°E - 94.50'; 5" Triple H. Maple - S40°W - 59.60'.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY David B. Babbitt CHIEF OF SURVEY PARTY DATE 6-26-80
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558