

1993

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On 12/28 1999
Mike DASHNI
Chairman

For corners in

MENOMINEE

(County)

Located in:

Corner Code #

1. Public Land Survey

T 38N R 26W

E-3

2. Property Controlling in Section

S

$$\begin{array}{c} \text{---} \text{---} \text{---} \\ \text{T} \quad \text{R} \end{array}$$

3. Miscellaneous Property in Se

S-

T **R**

4. Lot No. _____, Recorded Plat _____

5. Private Claims

I, WILLIAM LENCA, in a field survey on DECEMBER 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

ORIGINAL B.T.'s: Cedar, 14", N53°W, 36 lks
Cedar, 12", S53°E, 26 lks

Original Survey by George E. Adair in 1852. All original evidence for this corner has been destroyed by county road improvements.

PERPETUATION: Neil E. Hill, RLS No. 27447 recorded in LCRC No. 649, Book 2

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 1" dia. Iron rod in line with the centerline of county roads running West and Southeast from this location. There is also an old fence line running East from this location. This corner was also used by The Michigan Department of Transportation in a project dated July, 1984, Neil E. Hill - Survey Chief. This corner has been used by local surveyors in section subdivisions and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Berntsen A1NBF30 Monument stamped for corner:

12" dia. Blue Spruce	S24oE	99.65 feet
8" dia. Cedar	S16oW	52.88 feet
9" dia. Blue Spruce	S56oW	61.32 feet
9" dia. Cedar	N30oW	64.30 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are measured to nail in side of tree.

Signed by William F. Zuck

Date December 15, 1993

Surveyor's Michigan License No. 26461



FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1976
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993