

SURVEY & REMONUMENTATION

MAR 29 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On 12/28, 1999
Mike Davis RLS
Chairman

For corners in
MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T^{38N} R^{28W} E-10

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, William Lenca, in a field survey on Apr., 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

BK. 6 Pg. 35
RECEIVED FOR RECORD
28 DEC 1999 3:56:09 PM
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE, MI 49858

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1849: Original Survey by James H. Mullett - B.T.'s - Fir, 8" - N13°W - 18 lks.; Spruce, 10" - S13°E - 24 lks. All original evidence for this corner has been destroyed by logging activities.
- 1937: Survey Map by Hearl R. Hall, Surveyor, & J.A. Dinsmore, Reg. Engineer, states "Found Old 4 inch Cedar Post". This map is in the possession of Dan Deacon, Twp. Supervisor & owner of land surveyed.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered an old Squared Cedar Post at an ancient fence corner. The distance from this corner to the Section Corner 1/2 mile North is 2576.82 feet compared to the 1937 record measurement of 2580.5 feet. This corner has been accepted by local land owners for at least 62 years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe 30" long/3-1/4" dia. Alum cap stamped for corner location:

10" dia. White Pine	East	4.76 feet	Scr. NBT
20" dia. White Pine	S18°E	55.85 feet	Scr. NBT
9" dia. Hard Maple	S84°W	27.20 feet	Scr. NBT
7" dia. Norway Pine	N25°W	53.77 feet	Scr. NBT
Metal Survey Sign Post	South	0.9 feet	



NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca 26461
Surveyor's Michigan License No. _____

Date Dec. 18, 1999