

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>41N</u> N. S., R. <u>25W</u> E. W.	<u>K-12, K-11</u>
2. PROPERTY CONTROLLING IN SECTION_____	, T. _____ N. S., R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION_____	, T. _____ N. S., R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August 28, 19 84, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

<p><u>K-12</u> West 1/4 Corner of Sec. 36 Wood post Tamarack 10 - S20E -7Lks. Spruce 6-N82W-26Lks.</p>	<p><u>K-11</u> NW Sec. Cor. of Sec. 36 Wood post Cedar 14 - S3W-32Lks. Cedar 10 - N28E-26Lks.</p>
--	---

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-12

Found 2 old cedar post points (one of which I believe is the point of the original 1/4 post) N20°W-4.6 ft. from a 13" tamarack stump with very definite callouse grown into hack mark at the bottom of the lower face. The face itself is weathered away but there is no doubt that this is the stump of the original tamarack. B.T. A blazed 7" cedar with signatures dated as early as 1906 is about 20' west of this corner.

K-11 Set from stub of N.E. cedar O.B.T. Badly rotted but with a solid slab showing definite upper face & signs of a lower face with overgrowth. Many later axe marks on stub. Measurements north-east & south fit very well & swamp edge 1.00 ch. west and 0.25 chs. north fit very well.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-12 D.N.R. Mon.

6" cedar - S69°E-true
S44°E-compass-4.9'
7" cedar - S62°W-true
S87°W-compass-11.1'
4" cedar - N48°W-true
N23°W-compass-16.35'
3" cedar - N28°E-true
N53°E-compass-9.9'

K-11 D.N.R. Mon.

3" cedar - N59°E-true
N84°E-compass-13.0'
6" cedar - S31°E-true
S6°E-compass-13.95'
8" cedar - S45°W-true
S70°W-compass-11.9'
6" cedar - N82°W-true
N57°W-compass-13.35'

SIGNED BY

David B. Babbitt

DATE

9-12-84

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)

FOR STATE AND UNITED STATES AGENCIES