

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Missaukee

(County)

Located In

Corner Code #

1. Public Land Survey T 21N R 5W L 5
T _____ R _____
2. Property Controlling in Section S _____ T _____ R _____
S _____ T _____ R _____
3. Miscellaneous Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on Nov. 10, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

L5 – 1852 – GLO – A. Curtis – Set ¼ Post

1) Aspen 7" N85°E 58 L.

2) Elm 8" S50°E 71 L.

- 1907 – CSR – FB #40, p. 66 - J. D. McBain

Iron bolt 36 x 1" round

- 1967 – DNR Field notes – K. J. Ostling

¾" iron bolt

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

L5 – ¼ Corner common to Section 12 & 13, T21N, R5W – Fd. 1" x 3.5' long round iron bolt with 1 ½" head in low area with water. No GLO witnesses. Measured the following grid bearings and distances: N88°41'53"W 2620.56' (2660.46' – GLO, 2621' – KJO) to 'K5' and S88°41'53"E 2654.99' (2660.46' – GLO) to 'M5'. 1" Iron bolt accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L5 – Replaced 1" x 3.5' long bolt with Stamped 4" DNR Alum. Cap on 1" x 5' long galv. Iron pipe – Up 1'.

Set Blue Carsonite Post 1' SW

N3°W 15.43' to set N & T in W. side 8" Ash scribed 'XBT'

N82°W 27.83' to set N & T in S. side 12" R. Maple scribed 'XBT'

S43°W 34.76' to set N & T in NE side Tri. 10", 3" & 4" Maple

S87°E 55.92' to set N & T in S. side 13" R. Pine



Signed by:

Craig W. McVean

Date:

11/18/2010

Surveyor's Michigan License No.:

39088