

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Missaukee

(County)

Located In

Corner Code #

1. Public Land Survey	T	21N	R	5W	M8
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on Sept. 07, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

M8 – 1837 – GLO – J. Brink – Set ¼ Section Post

1) Pitch Pine 6" S18½°W 11 L.

2) Pitch Pine 5" N76¼°W 529 L.

- 1911 – H. M. Belknap – Fd. Stake lying down. No tree for new bearings. Set Cedar post w/ asbestos paint.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

M8 – ¼ Corner common to Section 24, T21N, R5W, & Section 19, T21N, R4W – Searched area for Cedar stake called for by Belknap. Dug a 6' E-W X 10' N-S hole at single proportional position. No evidence of corner or GLO witnesses. Set 4" DNR Alum. Cap on a 1" X 60" iron pipe midway and on line between corners 'M7' and 'M9'. Grid distance is 2632.58' vs. 2640' – GLO to 'M7' and 'M9'. DNR Mon. accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M8 – 4" DNR Alum. Cap on 1" X 60" long galvanized iron pipe.
Set Blue Carsonite Post 1' North

N51°E 4.83' to set N & T in SE side 4" W. Pine

S69°E 44.44' to set N & T in S side 7" W. Pine scribed 'XBT'

S09°W 64.03' to set N & T in E side 10" W. Pine scribed 'XBT'

S81°W 52.46' to set N & T in N side 6" W. Pine scribed 'XBT'



Signed by:

Craig W. McVean

Date:

11/18/2010

Surveyor's Michigan License No.:

39088