LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Missaukee	Located In	Corner Code #	
(County)			
1. Public Land Survey	T 21N R 5\	N M9	
2. Property Controlling in Section S	T R R		
3. Miscellaneous	_ ' '		
Property in Section S S	_ T R		Register of Deeds Stamp & File Number
4. Lot No: Record	ded Plat:		ABCDEFGHIJKLM
5. Private Claims:			2 - 6 - 5 4 3 - 2 1
I, <u>Craig W. McVean</u> , in a field surver equirements of PA 74, Michigan Pand 2 above were in conformance with current manual of survey instrinterior, Bureau of Land Managemer corner points mentioned in lines 3, 4 of the Michigan Board of Land Sestablished, re-established, monumer	A of 1970, the corner p with regulations and rule uctions of the United S at or by a decree of a Co and 5 above were in c surveyors or by a Dec	cints mentioned in lines 1 as therefore as required in States Department of the burt of Law and/or that the conformance with the rules cree of a Court of Law;	3 4 7 8 9
NOTE: Not more than 2 corne be recorded on this certificate		own and range, may	10 -30 - 29 - 28 - 27 - 26 - 25 - 11 - 12 - 31 - 32 - 33 - 34 - 35 - 36
w'			13
A. Description of original monum	nent and accessories	and/or subsequent resto	oration:
M9 - 1837 - GLO - J. Brink - Set Post 1) Pitch Pine 8" S23°W 10 L. 2) Pitch Pine 9" N71°W 25 L 1852 - GLO - Subdivision T21N, R4W - Corrected East from post - A. Curtis. 3) S. Pine 10" N66°E 50 L.; 4) S. Pine 8" S53°E 17 L 1911 - H. M. Belkap - Fd. US Bearings 5) Spruce Pine 7" S54°E 53; 6) Spruce Pine 6" N38½°E 54½ - No Date - Missaukee CSR - FB #39, p. 52 6) P. Pine 7" N38°E 55; 7) Oak 7" N18°W 67 5) P. Pine 8" S55°E 53		 1938 – M. Schaaf – SW, SE & NE Holes. West 19.54 (20.00 – GLO) to Spring 8) Green J. Pine 8" N7°W 34 9) Green Tw. J. Pine 8" & 9" N27°E 62 Latter – Co. Survey Wit. 1967 – DNR Cor. Record – LCRC #499 – K. J. Ostling. Fd. Old post at comer as est. by Cavanagh 1900/s. 2 Cavanagh wits in place and NW USBT in place with bench mark and notch. Very good original corner. Set Cons. Dept. Mon. 10) 7" J. Pine N50°W 24.2'; 11) 4" R. Pine S46°W 40.5'; 12) 8" B. Oak S72°E 29.3' 	
B. Description of corner evidence	e found and/or metho	od applied in restoring o	r re-establishing corner:
Witnesses as follows: #1 #6 - Fd. Fallen - 36.6' to	– gone; #2 – Fd. stp. centerline; #7 – Fd. S	. remains with piece with Stp. – 44.8' to centerline:	30, T21N, R4W – Fd. 4" DOC Alum. Cap on 1" iron pipe. In face and notch – 17.3' to centerline; #3, 4, & 5 – gone; #8 & 9 – Gone; #10 – Fd. Dead Stub; #11 & 12 – OK. position of the original comer.
C. Description of monument for	corner and accessor	ies established to perpe	tuate locating the position of the corner:
M9 - 4" Dept. of Conservation A Add W. Pine post 1' South Add Blue Carsonite Post 1' S47°W 40.76' to set N & T S16°W 25.04' to set N & T N2°W 42.78' to set N & T	n 1' East Γ in E. side 11" R. Pin Γ in E. side 8" R. Pine in N. side 12" Oak (#	e (#11) : :	CRAIG W. McVEAN PROFESSIONAL SURVEYOR No.
Signed by: Surveyor's Michigan License	M. M. 39088	how Do	ate: 1/18/2010 PESSIONAL SUFFICIENT