

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Missaukee
(County)

Located In

Corner Code #

- | | | | | | |
|--------------------------------------|---|-----|---|----|------|
| 1. Public Land Survey | T | 21N | R | 5W | I-10 |
| | T | | R | | |
| 2. Property Controlling in Section | S | T | | R | |
| | S | T | | R | |
| 3. Miscellaneous Property in Section | S | T | | R | |
| | S | T | | R | |

Register of Deeds Stamp & File Number

4. Lot No: Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on Oct. 8, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

I-10 – 1852 – GLO – A. Curtis – Set ¼ Post

1) Y. Pine 12" N77°W 26 L.

2) Y. Pine 14" S40°E 49 L.

- 1915 – CSR-FB#39, P. 71 & 79 – O.B. OK & remarked.

3) WPS 22" N35°E 1.25

- 1939- M. Schaaf – Block Set. SE Stp. marked by recent surveyor.

Corner falls in S. edge of Cut (Road) and LT South. NBT's –

4) NP Stp. 11 S18°E 55;

5) NP Bottom 12 N19°W 47

- 1992 – LCRC #843 – C. F. Roser

Set DNR Mon. and Cedar post from one Fd. M-Schaaf Stp.

(Pine Stp. S18°E 36.3' – We measure S14°E 36.3') and One Pine Stp. M. Schaaf called GLO wit. (Y. Pine 14" S40°E 26.4' GLO – We measure to Pine Stp. remains with lower notch S35°E 26.6'). This also fits fd. Pine roots from M. Schaaf wit to NW. Cor. falls 3' South of Center E-W Trail in cut area.

6) 15" Oak (Clp. 2) N55°W 43.3';

7) 6" Maple (Clp. 7) N5°E 34.5';

8) 11" R. Oak Due S 33.4';

9) 15" R. Oak S35°W 34.8'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-10 – ¼ Corner common to Sections 26 & 27, T21N, R5W – Fd. 4" DNR Alum. Cap per C. F. Roser. Centerline of Old E-W Road cut (Now ORV Trail) is 3' N. Measured S39°E 27.4' to centerline 14" YPS – Witness #2. Also S18°E 36.8' to centerline 11" NPS for witness #4. Found Pine Stp. remains at location of Witness #5. No evidence of Witnesses #1 or 3. Roser witnesses in place. DNR Monument accepted as a careful and faithful perpetuation to the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-10 – 4" DNR Alum. Cap on 1" iron pipe. Add Ring of Stones

Fd. Cedar post 1.5' to SW.

N5°E 34.75' to set N & T in W. side 7" Maple Clp. – 7. (#7)

South 34.25' to set N & T in E. side 15" Oak (#8)

S37°W 35.30' to set N & T in NW side 17" Oak (#9)

N55°W 44.01' to set N & T in NE side 18" Oak (#6)



Signed by:

Craig W. McVean

Date:

4/5/2010

Surveyor's Michigan License No.:

39088