

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MISSBAUKEE
(County)

Located In:

Corner Code ~~##~~

- | | | |
|---------------------------------------|-----------------------------|-------------------|
| 1. Public Land Survey | T <u>21N</u> R <u>6W</u> | <u>J-10, J-11</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling
in Section | S <u>26</u> T _____ R _____ | <u>12</u> |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous
Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, CARL F. ROSER, in a field survey on JUNE 17, 19 91,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
J-10 J-11 12

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-10	J-11	12
ESTABLISHED CTR OF SEC 26 AT INTERSECTION OF 1/4 LINES. CTR OF E-W TRAIL IS 9' SOUTH.	RESTORED S 1/4 COR OF SEC 26 FROM FD TWO US BT STPS; US= Y.PINE 13" N63 1/2°E, 4.6' AND Y.PINE 17", S62 1/4°E, 5.3'; STP TO NE IS MOSTLY GONE, ONLY BACK SIDE REMAINS. N-S WOODS TRAIL RD FROM SOUTH (NARROWS TO PATH ON N) IS WEST 51' ±.	SET NE COR OF SE 1/4 OF SW 1/4 OF SEC 26 PER STANDARD BLM INSTRUCTIONS.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-10	J-11	12
DROVE 5/8" X 34" REROD W/RLS CAP. SET CED POST W/LOC TAG.	SET DNR MON & CED POST. 10" MAPLE(CLP3) N02°E 30.8' 3" MAPLE N55°E 3.7' 4" MAPLE S32°W 44.6' 2" MAPLE S62°E 26.4' *15" Y PINE STP S62°E 5.2' *Y.PINE STP(PART)N63°E 5.2'	DROVE 5/8" X 34" REROD W/LS CAP & SET CED POST W/LOC TAG. 15" OAK N20°E 23.8' 8" TRPL MAPLE S07°E 77.2' 4" MAPLE S80°W 56.3' 7" MAPLE(CLP) N50°W 40.1'
12" B OAK NORTH 32.7'		
8" B CHERRY (CLP3) N65°E 26.9'		
13" R PINE EAST 113.6'		
3" BALSAM S55°W 40.1'		

*US B.T. STP REMAINS.

Signed by Carl F. Roser 12028 Date 12-02-92

Surveyor's Michigan License No. _____

