947

DEC 0 7 1994

Surveyor's Michigan License No. 33977

LIBER 290	ice 34
DOEK	\UC

	and the second of the second o	A D	LAND CORNE	R RECORDATION CE	ERTIFICATE	<i>-29</i> 0	PAGE
_	COMMISSI	CN	Filing Require	ement of Act 74, Micl	h. P.A. 1970 .	LIBER	PAGE
Fo	r corners in				1		
	Missaukee	Lo	cated In:	Corner Code ##		MISSAUKEE COL	INTY MICHIGA
	, 1000.11,7		0411 0111	F 4	ļ		, /
1.	Public Land Survey		21N R 8W	E-9		RECORDED OCT 2	8 1994 /
			R			,,,,,,	,
			R			Caroliga	40.
_	December Controlling		r			(audign	, Flan
2.	Property Controlling in Section		R				(LECTION
3	Miscellaneous		R		Donie.		
Ο.	Property in Sec.		R		negis	ster of Deeds Stamp &	File Number
	,						
	Lot No , I					ABCDEFG	
5.	Private Claims					2 6 6	ŢŢŢ
						3	
	I Dean Geers	in a field a	nou on Octobe	<u>er 7 · , 19 _ </u>	93	5	
ı, do	hereby certify that under re	avirements of P	A. 74, Michigan P.A.	of 1970, the corner points in	nentioned		
in I	ines 1 and 2 above were i	n conformance	with regulations and	d rules therefore as requir	red in the	6 18 17 16	—15——14——1 ——1
	rent manual of survey instr					7	1 1 1 1 1 1 1
	nagement or by a decree of ove were in conformance wi					8 19 20 21	-22
Co	urt of Law; established,	re-established.	monumented, re-n	nonumented, recovered,	found as	9	++
	pressed below:					10 30 29 28	27262
NO	TE: Not more than 4 c	orners, all in	the same town an	d range, may be record	ded	¹¹	- - - - - - - - - -
	on this certificate.	•		•	1	12 31 32 33	-34-353
						13	
Α.	Description of original	monument an	id accessories and	l/or subsequent restora	tion:		
	E-9) 1899 Beuthic long 3" in di E-9) 1899 Cavana E 60	en Survey in lameter place agh Survey	n Section 28: Coed in small ston in Section 29: I	ech 13 S 43 3/4 W 3 orner was used but t	ce post S 48	given; Cedar stake W 68, Maple 4 S	
В.	Description of corner e	vidence foun	d and/or method a	pplied in restoring or re	eestablishing co	orner:	
	Foun This	d Iron in ce	to Sections 20, enterline of East excepted as a care	21, 28 and 29 -West Road and ±6' ful and faithful perp	West of Nor etuation of the	rth-South centerline	e.
	ongi	nal corner.				•	
				•			
				•			
						ition of the corner	
C.	Description of monume	ent for corner	and accessories e	stablished to perpetual	te locating the	position of the corrier.	•
	E-9) Set 1/2" Iron	n and Missa	ukee Co. monu	ment in monument b	oox		ALIE CONTRACTOR
	•		n n '	Pe	er Group Revi	ewed and Approved-	MICHICA
		3 - 81.24 -	P. Pole	_		and the state of	AN TA
		V - 45.54 -			ite: <u>(0-0</u>	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	HS Y
		E - 41.87 -	Pk in East end Pk in West end		Dean Seers. Miss	aukee Co. Rapresentative	NO I
			- Set Iron in cer	· •		ME N	I ~ ₩
	301	14 - 123,31	- Oct Mon III CCI	icannic or road		339	

_ Date ____8/8/94