

SURVEY &
REMONUMENTATION

JAN 27 1999

LIBER 323 PAGE 1236

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

#1287

For corners in

<u>Missaukee</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>22N</u> R <u>06W</u>	<u>G-13</u>
	T <u> </u> R <u> </u>	
	T <u> </u> R <u> </u>	
	T <u> </u> R <u> </u>	
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	
	S <u> </u> T <u> </u> R <u> </u>	
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	
	S <u> </u> T <u> </u> R <u> </u>	

MISSAUKEE COUNTY MICHIGAN

RECORDED NOV 13 1998 9:50 A.M.

Carolyn Flors
REGISTER

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, J. Dean Geers, P.S., in a field survey on June, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

G-13) 1837 GLO Section Post by John Brink, Deputy Surveyor; Beech 11-N56½E-58, Beech 11-N53W-54
G-13) County Surveyor notes, stone; Maple 10-S27W-147½, WPS 40-S73E-48

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-13) Section Corner common to Sections 33 and 34, T22N, R6W and Sections 3 and 4, T21N, R6W; Found iron and cap as established by Dan Schripsema. The Corner is ± 4' west of Centerline N-S road. Excavated at the intersection but found no other evidence of Corner. A possible County Surveyor Witness remains S27W 146' to 60" Maple clump. This Corner is accepted as the best available evidence of the position of the original Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-13) Set ½" x 18" Iron and Missaukee County Monument
S73E 92.78 NW Corner Barn
N82W 38.79 8" Red Pine
S45W 59.23 8" Red Pine
N27W 69.80 10" Red Pine, Found Nail
East 62.67 Corner Fence Post

Peer Group Reviewed and Approved

Date: 10-4-98
J. Dean Geers
J. Dean Geers, Missaukee Co. Representative

Signed by *J. Dean Geers*
Surveyor's Michigan License No. 33977

Date 11-2-98

