

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Missaukee Located In: Corner Code #
(County)

1. Public Land Survey T 22N R 6W M-4
T R
T R
T R

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat

5. Private Claims

1208
LIBER 315 PAGE 1110
MISSAUKEE COUNTY MICHIGAN
RECORDED DEC 29 1997 1:25 PM
REGISTER
Register of Deeds Stamp & File
Number

I, Daniel E. Schripsema, in a field survey on October 1, 19 97
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner
points mentioned in lines 1 and 2 above were in conformance with regulations and rules
therefore as required in the current manual of survey instructions of the United States
Department of the Interior, Bureau of Land Management or by a decree of a Court of Law
and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance
with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law;
established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4			3		2	1
3													
4	7			8			9			10		11	12
5													
6	18			17			16			15		14	13
7													
8	19			20			21			22		23	24
9													
10	30			29			28			27		26	25
11													
12	31			32			33			34		35	36
13													

A. Description of original monument and accessories and/or subsequent restoration:

M-4) 1837 John Brink GLO survey set quarter post section 12; Hemlock 8 S54W 15, do 10 N59W 26
1913 Beuthien survey, FB #11, pg.77, iron stake, nothing to bear to
1914 Beuthien survey, FB #18, pg.79, iron stake and stone
1914 Beuthien survey, FB #34, pg.53, iron stake and stone in center of highway
1995 Daniel E. Schripsema survey, set 1/2" rebar and cap by single proration on line between NE and SE Section
corners using 1913 & 1914 surveys of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-4) Quarter corner common to Section 12, T22N, R6W and Section 7, T22N, R5W. Found 1/2" iron and cap.
This corner is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-4) Set Missaukee County Monument on existing 1/2" iron

N88W 33.04' 1/2" iron and cap
N14E 143.43' telephone ped. post
S88E 38.73' corner fence post
S16W 103.29' 6" Elm

Peer Group Reviewed and Approved

Date: 12-18-97
J. Dean Geers, Missaukee Co. Representative

Signed by Daniel E. Schripsema Date 12-2-97

Surveyor's Michigan License No. 24617



SURVEY &
REMONUMENTATION

JAN 16 1998

SECTION

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995