LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. PA 1970

For Corners In:		MAI 17 2006
Missaukee (County)	Located In Corner Co	de #
Public Land Survey	T 22N R 8W B7	
2. Property Controlling	T R	
in Section	S T R	
3. Miscellaneous	STR	
Property in Section	S T R	
	S T R	Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	—— A B C D E F G H I J K L M
5. Private Claims:		2 6 5 4 3 2 1
requirements of PA 74, Mi and 2 above were in conforthe current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established	field survey on July 12, 2005 do hereby state that chigan PA of 1970, the corner points mentioned in brance with regulations and rules therefore as requivey instructions of the United States Department anagement or by a decree of a Court of Law and/or lines 3, 4 and 5 above were in conformance with the function of Law and/or land Surveyors or by a Decree of a Court of Law and/or lines 3, 4 and 5 above were in conformance with the function of the Land Surveyors or by a Decree of a Court of Law and	lines 1 uired in to of the that the ne rules of Law; w: 1
A. Description of original monument and accessories and/or subsequent restoration:		
Sec. 18 Survey. (1 'A7'). Did this work	4°W 16 L. W 11 L. D. Records – F. Bk 70, p. 41 – Teed – 1886 B7') Last established by running E-G ('C7'- ⟨ carefully. W. Pine 20" N52½°E 9. les A. Ray – 1989 – fd. rifle barrel per residents. € 11.68'	N60°E 14" Poplar 29.30' S50°E 12" R. Pine 46.51 - Unrecorded Survey LCM Job #032077 - 2003 Sec. 19 survey William E. Sikkema Fd. ¾" shaft N13°W 84.18' 6" White Pine S85°W 27.55' 4" Oak S2°E 58.83' 6" R. Pine N79°E 17.99' 4" White Pine
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:		
B7 – ¼ corner common to Sections 18 & 19, T22N, R8W - Found 7/8" x 1.9' long octagonal rifle barrel and all witnesses of James A. Ray & W. E. Sikkema. Measured West 100'± vs. 165' – GLO to edge of swamp. Measured W 323'± vs. 396' – GLO to W. Bank Stream. From rifle barrel measured East to 2638.6' vs. 2640' – GLO to 'C7'. Measured West 2564.9' vs. 2640' – GLO to 'A7'. Teed's distance between 'A7' and 'C7' is 5296.5'. N85°E 79.5' of rifle barrel set a spike from found 20" WPS w/ notch which appears to be Teeds 1886 BT to his established position. For Teed's 'B7' position to be valid – 'C7' position – would need to move 80' + East of its existing position. Based on aerial photos from 1938 – 'C7' position has been occupied since then at its current position. No evidence of any other position 76' to 93' East of 'C7' per Teed and GLO Distances. Rifle barrel is accepted as the best available evidence of the position of the original corner.		
C. Description of monur	nent for corner and accessories established to	perpetuate locating the position of the corner:
B7 – Set 4" stamped aluminum DNR cap on 1" x 36" galv. iron pipe over fd. 7/8" octagonal x 1.9' long rifle barrel. N45°E 29.25' to fd. nail in SE side 13" poplar (JAR) N70°W 11.75' to set N & T in S. side 17" Red Pine (JAR) South 30.98' to set N & T in E. side 24" Red Pine scribed 'XBT' (JAR) S46°E 46.51' to set N & T at found nail in SW side 18" Red Pine (JAR) West 27.54' to set N & T at found nail in S. side 5" Oak (WES) N17°W 84.18' to set N & T at found nail in W. side 7" White Pine (WES) Set 1 ½" I.D. cyclone fence post 1' South Set Blue Carsonite Post 1' NE. No. No. 39088		
Signed by:	W.M. Vean	Date: 5/11/2006
Sulveyor's Michigan	Li g ense No.: 39088	