

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Missaukee
(County)
Located In
Corner Code #
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Section
4. Lot No:
5. Private Claims:

I, Craig W. McVean, in a field survey on July 22, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Table with 13 rows and 13 columns (A-M). Contains a grid of numbers 1-36 and two black dots in row 7, column B and C.

A. Description of original monument and accessories and/or subsequent restoration:

- 1 - 1886 - CSR - Teed Notes - Wexford Co. Records - FB.20, p. 41 - W. Pine 30" N45°E 2 L.
- 1997 - Unrecorded Survey - Pearson & Case - Job # 97277 Paul A. Trinklein - Set Iron
2 - 2003 - Unrecorded Survey - LCM Surveying - Job # 032077 - William E. Sikkema PS #45505 - Set PK nail.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- 1 - W 1/16, Cor. common to Sections 18 & 19, T22N, R8W - Fd. 1/2" x 18" capped iron rod per Unrecorded Survey. Also searched for Teed's position. At N84°E 44' from 1/2" CIR found centerline sheared off WPS at W. edge of 2-track. Dug at SW side of WPS but no corner evidence. 1/2" x 18" CIR accepted as best available evidence of the position of the corner.
2 - E 1/16, Cor. common to Sections 18 & 19, T22N, R8W Fd. mag nail 4.0' South of painted Centerline of Kelly Rd. per Unrecorded LCM survey. Pk nail accepted as best available evidence of position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- 1 - Replaced 1/2" x 18" CIR with stamped 2" Aluminum Cap on 5/8" x 34" rebar.
N20°W 38.83' to set N & T in W. side 11" R. Maple
N40°E 28.11' to set N & T in SE side 11" R. Maple
S66°E 23.27' to fd. nail in N. side 5" Oak
S20°E 36.80' to fd. nail in W. side 8" B. Cherry
Set Blue Carsonite Post with location tag 1' SE
2 - Replaced mag nail with stamped 2" aluminum cap on 5/8" x 34" rebar, flush with bit surface
N16°W 46.55' to set N & T in E. side 12" R. Pine
N70°W 70.45' to set N & T in SW side 13" R. Pine
S28°E 31.80' to set N & T in SW side P.P.
South 33.04' to found 1/2" capped iron rod #45505
North 33' to set Blue Carsonite Post with Location tag

Signed by: Craig W. McVean
Surveyor's Michigan License No.: 39088

Date: 5/11/2006

