

# SURVEY & REMONUMENTATION

MAY 28 1997

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

#1103

LIBER 308 PAGE 896

For corners in

Missaukee County Located In: Corner Code #  
(County)

1. Public Land Survey T 22N R 7W C-13  
T    R     
T    R     
T    R   

2. Property Controlling S    T    R     
in Section S    T    R   

3. Miscellaneous S    T    R     
Property in Sec. S    T    R   

4. Lot No.       , Recorded Plat       

5. Private Claims       

MISSAUKEE COUNTY MICHIGAN

RECORDED DEC 30 1996 1/30 PM

*Carolyn Klose*  
REGISTERED

Register of Deeds Stamp & File  
Number

I, Daniel E. Schripsema, in a field survey on October 1, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:

C-13) 1837 GLO survey by John Brink, Deputy Surveyor - set post corner Sections 31 & 32 - Beech 10" N27E 46, Beech 8" N50W 28  
1898 survey pg. 63 county surveyor notes - sec. 6, iron stake N33E 57 1/2  
1899 survey pg. 62 county surveyor notes - sec. 5, shown but no comment or witness  
1890 survey pg. 77 county surveyor notes - sec. 31, iron stake fe. post N33E 57 1/2  
1889 Matthew McClung LCRC - No. 785. Found 3/4" rod - Tel. Box N45W 41.8', 3" spruce N40E 63.0', 6" w. pine S55E 59.25'  
1889 Matthew McClung survey, liber S2, pg. 461  
1991 J.L. Wilcox survey, liber S3, pg. 61, Found 3/4" rod - 2' E. of centerline N&S road and 6' S. of centerline E&W road,  
N46E 44.96' corner fe. Post, S46W 59.16' 8" w. pine, S57W 40.07' 8" w. pine, N50W 50.71' 5" cherry

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-13) Section corner common to Sections 31 & 32, T22N, R7W, and Section 5 & 6, Found 3/4" iron of record. This corner is accepted as careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Set Miss. Co. remonumentation cap on existing iron.  
S43E 59.12' 8" White Pine (Fd Nail)  
N50E 44.95' Corner Fence Post (Fd Nail)  
N42W 41.68' Phone Riser  
N47W 50.73' 6" Cherry (Fd Nail)  
N24E 97.25' Power Pole

Peer Group Reviewed and Approved

Date: 12-30-96  
*J. Dean Geers*  
J. Dean Geers, Missaukee Co. Representative

Signed by Daniel E. Schripsema

Date 12-30-96

Surveyor's Michigan License No. 24617