LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	
Missaukee Located In: Corner Code #	
1. Public Land Survey	
2. Property Controlling STR	
in Section S T R	
3. Miscellaneous S T R	Register of Deeds Stamp & File Num
Property in Sec. S T R	
4. Lot No, Recorded Plat	ABCDEFGHIJKLM
5. Private Claims	2 6 5 4 3 2 1
	4 - 7 - 8 - 9 - 10 - 11 - 12 -
I, Craig W. McVean , in a field survey on February, 25 19 97 do	5
hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and	
rules therefore as required in the current manual of survey instructions of the United	6 18 17 16 15 14 13
States Department of the Interior, Bureau of Land Management or by a decree of a	
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were	819 20 21 22 23 24
in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered,	9
found as expressed below:	10 30 29 28 25
	11
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	12 31 32 36 36 36
A. Description of original monument and accessories and/or subsequent restoration:	
I-9 - GLO - Set Post - A. Curtis - 1852 B. Ash 10" N73°W 12L B. Ash 15" S18°E 26L - Co. Surveyor Notes - Book 23, Page 60 - Stake-J. McBain-No date	
B. Ash 8" S51°W 14L Maple 10" S48°E 21L B. Ash 8" N17.5°E 35L	
- Co. Surveyor Notes - 1915 - Book 24, Page 64 - O.B. OK, set new post - Co. Surveyor Notes - Book 24, Page 52 - O.B. OK : NB S. Maple 12" S60°E 22L	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
I-9 -Section Cor. common to Sec. 22,23,26 & 27-Excavate 6' + diameter hole in swamp. Nothing conclusive found. Set 4" DNR A.C. on 1" X 8' long Iron Pipe by doubling distance up from I-10 thru N 1/16 cor. on W. line of section 23 at location of excavation. One possible Old-NBT fits this location. Monument accepted as the best available evidence of the position of the original corner.	
C. Description of monument for corner and accessories established to perpetuate locating the	e position of the corner:
I-9 - 4" Alum. cap on 1"x8' pipe. Set blue carsonite post 1' West. S50°W 9.33' to set nail and tag in center of core remains of 14"+ hardwood stur S82°W 20.44' to set nail and tag in S side 6" R. Maple scribed "XBT" N35°W 27.50' to set nail and tag in W side 14" R. Maple scribed "XBT" S70°E 47.27' to set nail and tag in SW side 13" Ash scribed "XBT" S04°W 62.84' to set nail and tag in E side 22" R. Maple scribed "XBT" N41°E 12.98' to set nail and tag in E side 4" Ash scribed "XBT"	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR
$\alpha : \alpha : \alpha : \Omega$	No. 39088
Signed by Crave W. My Van-	Date 3/6/1998
Surveyor's Michigan License No. 39088	. ————————————————————————————————————