

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Missaukee County
(County)

Located In:

Corner Code #

1. Public Land Survey

T 23N R 6W

M-2

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

#1212
LIBER 315 PAGE 1114
MISSAUKEE COUNTY MICHIGAN

RECORDED DEC 29 1997 125 PM

Register
REGISTER

Register of Deeds Stamp & File
Number

I, Daniel E. Schripsema, in a field survey on October 1, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

M-2) 1839 GLO survey set quarter post section 1; 8" diameter Cedar named corner
1992 Carl F. Roser LCRC, #858; Set 5/8" rerod w/ cap
P. Pole S15W 124.68', 12" Tamarack S60W 97.36', 11" Tamarack West 96.6', 13" Tamarack N45W 123.9',
Set Cedar Post w/ tag West 33.0'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-2) Found 5/8" rerod / cap of record, LCRC #858. Corner falls 1' East of centerline of N & S road. This corner is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-2) Set Missaukee County monument over exiting 5/8" rerod and added monument box

N45W 124.81' 13" Tamarack
West 97.05' 12" Tamarack
S59W 97.69' 12" Tamarack
S14W 124.66' Power pole
West 32.68' DNR cedar post

Peer Group Reviewed and Approved

Date: 12-18-97
J. Dean Geers, Missaukee Co. Representative

Signed by Daniel E. Schripsema

Date 12-2-97

Surveyor's Michigan License No. 24617



SURVEY &
REMONUMENTATION

JAN 16 1998

SECTION

APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1996