

**,Land Corner Recordation Certificate
Attachment B to 2017 Annual Grant Agreement
Authority: MCL 54.205 and R54.202**

This form is **ONLY** for corners filed under the 2017 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2017 State Survey and Remonumentation Grant Agreement

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Missaukee County

Forest Twp.

| Corner Type | Survey Township | Corner Code |
|--------------------------------------|-------------------------|-------------|
| Original Public Land Survey Corner | T 23N R 7W | H7 |
| • MCL 54.202(g) | T _____ R _____ | _____ |
| • MCL 54.262(g) | T _____ R _____ | _____ |
| Property Controlling Corner | S 15,22 T 23N R 7W | Near H7 |
| • MCL 54.202(i) | S _____ T _____ R _____ | _____ |
| • MCL 54.262(h) | S _____ T _____ R _____ | _____ |
| Protracted Public Land Survey Corner | T _____ R _____ | _____ |
| • MCL 54.202(k) | T _____ R _____ | _____ |
| • MCL 54.262(i) | T _____ R _____ | _____ |

| | | | | | | | | | | | | | | |
|----|----|---|----|---|----|---|----|---|----|---|----|---|----|----|
| 1 | A | B | C | D | E | F | G | H | I | J | K | L | M | 1 |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | 2 | |
| 3 | | | | | | | | | | | | | | 3 |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | 4 | |
| 5 | | | | | | | | | | | | | | 5 |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | 6 | |
| 7 | | | | | | | | | | | | | | 7 |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | 8 | |
| 9 | | | | | | | | | | | | | | 9 |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | 10 | |
| 11 | | | | | | | | | | | | | | 11 |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | 12 | |
| 13 | | | | | | | | | | | | | | 13 |
| | A | B | C | D | E | F | G | H | I | J | K | L | M | |

Part A: Corner(s) History

H7 – ¼ Corner common to Sec. 15 & 22, T23N, R7W –

- 1853 – GLO – Set Post – T. Whelpley

1) Tamarack 12" N16°E 17 L.; 2) Cedar 8" S84°W 10 L.

- 1981 – LCRC # 665 – J. L. Wilcox PS # 14102

Set iron and cap in ½' of water by single proportion.

3) N22°W 5" Cedar 4.22'; 4) N65°W 3" Cedar 7.48'; 5) S48°W 5" Cedar 5.88'; 6) S06°W 5" W. Birch 10.49'

Part B: Surveyor's Report on Perpetuation or Monumentation of Corner(s)

H7 – ¼ Corner common to Sec. 15 & 22, T23N, R7W – No GLO evidence was found. Set stamped 4" DNR Aluminum Cap on 1" x 4' long galvanized iron pipe by single proportion between 'I-7' and reestablished 'G7'. Corner in Cedar swamp. Grid distance East and West is 2642.51' vs. 2640' – GLO. DNR Monument accepted as a careful and faithful reestablishment of the position of the original corner.

PCC near H7 – Fd. ½" capped iron #14102 is N89°02'W 24.64' from 'H7'. Could not accept this iron as 'H7' since it is based on rejected position at 'G7'. This property controlling corner is recorded by this surveyor strictly to comply with the requirements of P.A. 74 of 1970 as amended and P.A. 345 of 1990 as amended and is not an endorsement of the corner position.

