

MAY 28 1897

O LAND SUR

LAND CORNER RECORDATION CERTIFICATE

		COM	MOICEM	Filing Requ	iremen	t of Act 74, Mic	ch. P.A.	. 1970	#/	255	7
	corners ir Missaul		Locat	ted in:		Corner Code #	1	MIS	SSAUKEE COUN		CHIGAN
2.	Property of in Section		T T ST ST ST	24N R 6V		E-7		RECOV	DEC 20	1996 Flu	975 M. Selster
	t at Na		Decembed Dist				_				
I, _do hin lir	J. Dea nereby certines 1 and 2 nual of sur	n Geers fy that under above were i	, in a field surverequirements of Ponconformance with the United of a Court of Lav	ey on	Cember P.A. of 19 ad rules the ortment of	970, the corner policerefore as required f the Interior, Bur oints mentioned in	9 <u>76</u> Its mentic in the cu eau of l lines 3, 4	2 3 4 , 5 oned 6 rrent Land 7	A 8 C D E F	10- 15- 1-22-	J K L 2 11 12 12 14 13 14 13 14 13 14 13 14 13 14 13 14 15 15 16 16 16 16 16 16 16 16 16 16 16 16 16
5 at	oove were	in conforman	ce with the rules	of the Michigan	Board of	Professional Surv	eyors or	bya o			
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.								10 11 12			35 36
A.	Description of original monument and accessories and/or subsequent restoration: E-7) 1853 GLO Section post by Whelphley; Beech 6-N47½E-36, Hemlock 20-S28 3/4W-23 E-7) 1899 County Survey Notes; Found Old corner stake, Maple 12-N47E-50, Beech 14-S54W-63 E-7) 1913 County Survey Notes; Found Corner; Maple 18-N71W-49 E-7) 1934 County Survey Notes; Corner was used but no new witnesses. E-7) 1979 Fauser Survey, Liber S-1, Page 45; Found 1/2" rebar in intersection, Tele Pole-S45W-39.85, Tele Pole - N55E-60.85, Road Sign Post-N30E-51.00 E-7) 1980 Wilcox LCRC, Liber 1, Page 585; Found 1/2" rebar in intersection, S44W-39.93-Tele. Pole, N49W-94.62-3" Ash, N68E-60.83-Tele. Pole, S20E-77.80'-Sign Post E-7) 1992 Mitchell Survey, Liber S-3, Page 140; Found 1/2" Road in Intersection, S44W-39.93-Tele. Pole, N49W-94.62-3" Ash, N68E-60.83-Tele. Pole, S20E-77.80'-Sign Post										
B.	Descript	ion of come	r evidence four	nd and/or metl	hod appl	lied in restoring o	or reesta	ablishing corr	ner:		
	E-7)	Corner is ±	l' South of East-V	West Centerline	Road and	21, T24N, R6W. ±2' West of North of the original of	-South C	1/2" rebar of re Centerline. Th	ecord in intersecti is corner is accep	on. ted	
•					ν.						
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:											
	TI div	g - 1 /o # *	m wilth h Caraci	aa Cauntu Ma-	,						
	E-7)	Set 1/2" ire	on with Missauk	ee County Mon	l.			•			
		N58E N35W	72.90 - Set wit. - 63.78 - Post @ - 81.53 - 8" As - 100.01 - 12" A) Tele. Riser pen				Date 18-	Reviewed and 19-96 Occ. Description of the Republic Repub		_
Sig	ned by	(<u></u>	On O	2 1/2		· · · · · · · · · · · · · · · · · · ·	Date_	12-19-5	6	·····	
Surveyor's Michigan License Non 33977 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 23, 167 REVISED MAY 14, 197 REVISED JAN., 198											