

MAY 28 1997

LIBER 308 PAGE 693

LAND CORNER RECORDATION CERTIFICATE

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Missaukee
(County)

Located in:

Corner Code #

#1062

MISSAUKEE COUNTY MICHIGAN

RECORDED DEC 20 1996 713 M.

Carolyn Klare
REGISTER
Register of Deeds Stamp & File Number

1. Public Land Survey	T	<u>24N</u>	R	<u>6W</u>	<u>H-75</u>
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S		T	R	
	S		T	R	
3. Miscellaneous Property in Section	S		T	R	
	S		T	R	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, J. Dean Geers, in a field survey on December, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7								●					
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		

A. Description of original monument and accessories and/or subsequent restoration:

- H-7) 1853 GLO Quarter Section post by Whelphley; B. Ash 12-S54W-32, Hen 9-N39½E-13
 H-7) 1972 Erickson LCRC, Liber 1, Page 77; Found Iron 1' below surface, 1.2' North of centerline. Raised with small boat spike; N45W-6" J. Pine - 58.42, N45E-6" W. Pine-63.28, S 60E-T.Pole-46.25
 H-7) 1972 Ostling LCRC, Liber 1, Page 51; Found boat spike, N45W-6" J. Pine - 58.42, N45E-6" W. Pine-63.28, S 60E-T.Pole-46.25
 H-7) 1973 Radcliffe LCRC, Liber 1, Page 164; Found Boat Spike; P.P. -S60E-46.27, P.P. S55W-37.39, 8" W. Pine - N25W-70.53
 H-7) 1978 Granger Survey, Liber S-1, Page 394; P.P.-S60E-46.27, P.P.-S55W-37.39, 8" W. Pine-N25W-70.53

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- H-7) Quarter section corner common to Sections 15 and 22, T24N, R6W. Found 1" Iron of Record 2.5' below surface, $\pm 1'$ North of East-West centerline and $\pm 5'$ West of North-South Centerline Roads. This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- H-7) Set 1/2" Iron with Miss. Co. Mon.
S60W - 37.72' - P.P.
S10E - 50.36' - 6" Aspen
N45E - 64.63' - 16" W. Pine
N 35W - 55.08' - 3" Cedar

Peer Group Reviewed and Approved

Date: 12-19-96
J. Dean Geers
J. Dean Geers, Missaukee Co. Representative

Signed by J. R. [Signature]
Surveyor's Michigan License No. 33977

Date 12-19-96

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 20, 1971
REVISED MAY 14, 1975
REVISED JAN. 1983