MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey of Section 14. Found 2"x2" angle iron in place in center of E-W road and in line with fence north and old road grade south. Appeared acceptable as section corner, no evidence to the contrary. Probably established in 1909 Cavanagh survey.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED -

SIGNED Kenneth Joseph DATE 8/7/61