

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Missaukee Located In Corner Code #
 (County)

1. Public Land Survey T _____ R _____
 T _____ R _____

2. Property Controlling
 in Section S 2 T 24N R 8W 8
 S _____ T _____ R _____

3. Miscellaneous
 Property in Section S _____ T _____ R _____
 S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

Register of Deeds Stamp & File Number

I, Joshua R. Davidson, in a field survey on November 7, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

8 – CW 1/16 corner of section 2

None.

2014-00522 L: L-7 P: 2338 L: CORNER
 02/14/2014 09:09:33 AM Page 1 of 1
 Carolyn Flore County Recorder, Missaukee County MI



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

8 – CW 1/16 corner of section 2

Found 1/2" rebar and cap #24617. Accepted found rebar and cap as the best available evidence of the position of the corner and replaced it with a stamped 2" aluminum cap on 5/8" x 34" rebar.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

8 – a stamped 2" aluminum cap on 5/8" x 34" rebar

N22°E 43.64' to set nail & tag is E. side 4" Oak
 N68°E 32.66' to set nail & tag in SE. side 19" Triple Oak
 S04°E 28.56' to set nail & tag in W. side 6" W. Pine
 N58°W 4.65' to set nail & tag in NE. side 4" Maple
 Set blue post with location tag 1' East



Signed by:

Joshua R. Davidson

Date:

2/14/2014

Surveyor's Michigan License No.:

46659