

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Missaukee Located In                      Corner Code #                       
(County)

1. Public Land Survey T 24N R 8W C8  
T            R                        
2. Property Controlling in Section S            T            R                        
S            T            R                        
3. Miscellaneous Property in Section S            T            R                        
S            T            R                      

4. Lot No:                      Recorded Plat:                     

5. Private Claims:                     

I, Craig W. McVean, in a field survey on April 16, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

C8 – 1853 – GLO – T. Whelpley – Set ¼ Post  
1) W. Pine 4" N53 3/4"E 17 L.  
2) Beech 8" S54 ¼"W 21 L.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C8 – ¼ Corner common to Section 19 & 20, T24N, R8W – No conclusive GLO evidence was found. Set DNR Monument by single proportion to GLO between found corner 'C9' and reestablished corner 'C7'. From set DNR Mon. 3 possible White Pine Line tree stumps were found as follows: (GLO – South 9.55 Ch [630.3'] W. Pine 30") – 30"± WPS @626' S and 5' E of line; 18" ± WPS @ 634' S and 4' W of line and 24"± WPS @ 634' S and 8' West of Line. Grid distance N & S from DNR Mon is 2653.04' (2640' – GLO). DNR Mon. accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C8 – 4" DNR Alum. Cap on 1" x 36" long galv. iron pipe.  
Place 2 large stones on NW & SE sides of monument.  
Set Cedar post 1' North  
North 19.00' to set N & T in W. side 20" Oak scribed 'XBT'  
N47°E 53.20' to set N & T in N side 12" R. Pine scribed 'XBT'  
S5°E 21.50' to set N & T in E. side 13" W. Pine scribed 'XBT'  
S85°W 63.39' to set N & T in S. side 10" W. Pine scribed 'XBT'



Signed by:

*Craig W. McVean*

Date:

12/16/2010

Surveyor's Michigan License No.:

39088