

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Missaukee
(County)

Located In

Corner Code #

1. Public Land Survey	T		R	
	T		R	
2. Property Controlling in Section	S 19	T 24N	R 8W	8
	S 19	T 24N	R 8W	9
3. Miscellaneous Property in Section	S	T	R	
	S	T	R	

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on May 17, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

8 -None

9 -None.



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

8 - CW 1/16 Corner Section 19 - Set stamped 2" Aluminum cap on 5/8" x 48" rebar per Standard BLM procedure. Corner in Cedar swamp.

9 - CE 1/16 Corner Section 19 - Set stamped 2" Aluminum cap on 5/8" x 34" rebar per Standard BLM procedure. North 8'± to centerline E-W 2-track

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

8 - Stamped 2" Aluminum cap on 5/8" x 48" rebar
N27°E 20.11' to set Nail & Tag in E. side 12" Red Maple
S45°W 23.22' to set Nail & Tag in NW side 7" Cedar
S24°W 32.89' to set Nail & Tag in E. side 7" Red Maple
S30°E 23.37' to set Nail & tag in NE side 9" Cedar
Set Cedar post with location tag 1' West

9 - Stamped 2" Aluminum cap on 5/8" x 34" rebar
N73°E 61.14' to set Nail & Tag in NW side 12" Red Pine
S20°E 37.82' to set Nail & Tag in E. side 12" Oak
S52°W 13.60' to set Nail & Tag in SE side 12" White Pine
N08°E 25.76' to set Nail & Tag in W. side 12" White Pine
Set Cedar post with location tag 1' Southeast

Signed by:

Craig W. McVean

Date:

1/19/2011

Surveyor's Michigan License No.:

39088