LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

| For Corners In: Missaukee (County) | | Locate | đ In | Corner Code # | |
|--|---|---|--|---|---------------------------------------|
| 1. Public Land Survey | | T 24N | | | |
| 2. Property Controlling in Section | s · | т | R | | |
| 3. Miscellaneous | S | Τ | R | | |
| Property in Section | s | т т | R | - | Register of Deeds Stamp & File Number |
| 4. Lot No: | | | | | A B C D E F G H I J K L M |
| 5. Private Claims: | | | | | 2 -6 -5 -4 -3 -2 -1 -3 |
| I, <u>Craig W. McVean</u> , in a fier requirements of PA 74, Mic and 2 above were in confort the current manual of survinterior, Bureau of Land Mar corner points mentioned in I of the Michigan Board of established, re-established, | higan PA of mance with r rey instruction nagement or lines 3, 4 and Land Surve | 1970, the oregulations of the by a decreal 5 above wayors or by | corner points and rules the United State e of a Court overe in confor y a Decree | mentioned in lines 1 erefore as required in s Department of the of Law and/or that the rmance with the rules of a Court of Law; | 4 |
| NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. | | | | | 10 -30 -29 -28 -27 -26 -25 |

- A. Description of original monument and accessories and/or subsequent restoration:
- <u>J3</u> GLO Set ¼ Post T. Whelpley 1853 Beech 8" S35½°E 16 L. Beech 5" N10½°E 23 L.
 - DNR Cor. Rec. and LCRC #330 K.J. Ostling 1967
 Set 1" pipe w/ 4" Alum. Cap by prop. meas. midpoint on line between Sec. Cor. Nothing left for original evidence. 12" R. Oak S40°E 19.3'; 12" Tw. R. Oak N20°W 39.1'
- LCRC #689 R.F. Mitchell 1983
 Fd. 1" Iron pipe and Dept. of Conservation cap S35°E 16" R. Oak 19.76'
 N20°E 3" Maple 20.75'
 N55°W 2" Maple 15.8'
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- <u>J3</u> ½ Corner common to Sec. 2 & 11 Fd. 4" DOC (DNR) Alum. Cap on 1" iron pipe per Ostling and Mitchell. Fd. monument is 3.38' E. of SP position. Terrain to East is hilly while terrain West is more flat so felt position was accepted based on methods used to establish in 1967. DOC Mon. accepted as a careful and faithful re-establishment of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- J3 4" DOC (DNR) Alum. Cap on 1" Iron pipe
 N24°W 39.78' to set N & T in W. side Tw. 16" W. Oak (KJO)
 S42°E 19.80' to set N & T in E. side 16" R. Oak (KJO, RFM)
 N68°E 31.18' to set N & T in S. side 10" W. Oak scribed 'XBT'
 S80°W 29.28' to set N & T in N. side 5" R. Maple
 N60°W 15.81' to fd. nail in NE side 4" R. Maple (RFM)
 Set blue carsonite post 1' N.

CRAIG W.

* McVEAN

PROFESSIONAL
SURVEYOR
No.
39088

Signed by:

Surveyor's Michigan License No.:

Me U san

Date:

te: 5/20/2004