
LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Missaukee		Located In			Corner Code #												
(County)		•															
1. Public Land Survey		T -	24N	R 8W	K7												
2. Property Controlling in Section	S	Т		R													
000,011	s	Т		R													
Miscellaneous Property in Section	s	Т		R				Regi	iste	r of	Deed	ls Si	amn	& Fi	le N	uml	her
	s	T		R													
4. Lot No:	Recorde	d Plat	t:			_ 1	А В	С	<u> </u>	E	F	G	H I	J	к	Ļ	N
5. Private Claims: _						2 - 3	-6		-5-			Ė	<u></u>	— ź	\exists	- <u>(</u>	_
I, <u>Craig W. McVean</u> , in a requirements of PA 74, Mi and 2 above were in conforthe current manual of sur	chigan PA o	of 1970 h regul	0, the clations	corner points and rules the	mentioned in lines 1 erefore as required in	5	7 18		-17-		-9 — -16		10	—11 —11		12 	

Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

K7 - GLO - Set Post - T. Whelpley - 1853

Beech 10" N78°E 34 L. Beech 10" S423/4°E 47 L Beech 10" S291/2°W 28 L.

- CSR D.E. Teed 1901 Pump N61¾*E 34
- CSR J.G. Cavanagh 1909 Fd. Old stake and Gov't Wit's. - Set RR iron; Cedar stake N291/2 W 21; Hem. 20" S781/2°E; Pump N613/4°E 34
- DNR Cor. Rec. K.J. Ostling 1961 Fd. 4" RR rail in place on S. shoulder E-W Road. No Wit's left but this point checks line W & N. 20" Cherry S87"W 289.3'; 20" Cherry N171/2°W 283.4"
- LCRC #577 J.L. Wilcox 1979 Fd. narrow gauge railroad iron; S5°W fence post 29.15'; S25°E Cor. fence post 32.89'; N30°E 8" N. Pine 44.74'; N35°W 4" J. Pine 52.27
- LCRC #616 C.F. Roser 1981 Fd. 4" RR rail (vertical) buried on S. edge E-W dirt road. 9" R. Pine N42°E 44.76'; 4" S. Pine N18°W 52.30'; Fn. Post S12°W 29.15'; 26" Cherry S85°W 289.4'; Ctr. E-W gravel road N-7'±; set cedar post N 40'
- LCRC #712 J.L. Wilcox 1986 Fd. RR iron 8'± S. of centerline E-W gravel road and 13'± W. of N29°E 5" J. Pine 52.31'
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- K7 Sec. Cor. Common to Sec. 13, 14, 23 and 24 Fd. leaning ½" x 1' long iron rebar near surface. Removed and found railroad rail iron - Down 1.3' - Vertical but leaning N'ly a bit. Fit one found witness by Roser and Wilcox. Other witnesses mostly fallen or gone. Remains of fence S is 13'± E. Centerline of E-W gravel road is 7'± N. RR rail accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K7 - Raised RR rail iron w/ 2 1/2" stamped DNR Brass Cap on 5/8" x 8" iron rebar w/ 4" x 9" long PVC w/ conc. around cap.

N35°W 53.41' to fd. nail in SW side 10" J. Pine

N36°E 44.77' to fd. nail in NW side 15" R. Pine and add scribed 'XBT' (JLW, CFR)

North 50' to set blue carsonite post w/ loc. tag

N62°E 83.78' to set N & T in SE side 10" R. Pine scribed 'XBT S12°E 57.60' to set N & T in W. side 8" R. Pine

OF MICHIGAN CRAIG W. McVEAN ROFESSIONAL SURVEYOR No. 39088 POFESSIONA

Date:

Signed by:

Surveyor's Michigan License No.:

39088