

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Missaukee

(County)

Located In

Corner Code #

1. Public Land Survey	T		R	
	T		R	
2. Property Controlling in Section	S	12	T	24N
	S	12	T	24N
			R	8W
			R	8W
3. Miscellaneous Property in Section	S		T	
	S		T	
			R	
			R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on Jan. 12, 2004 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

8 - CSR - E.A. Beuthien - 1914

10 - None

Set Cedar Post

WPS N53°W 15

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

8 - CW 1/16<sup>th</sup> of Section 12, T24N, R8W - Found no evidence of CSR cedar post or WPS BT. Set 2" Aluminum cap on 5/8" x 34" rebar per standard BLM procedure.

10 - South 1/16<sup>th</sup> Corner common to Section 11 and Section 12, T24N, R8W - Set 2" Aluminum cap on 5/8" x 34" rebar per standard BLM procedure. S74°W 34' ± to fd. fence cor. remains.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

8 - Set 2" stamped Aluminum cap on 5/8" x 34" iron rebar.

Set Blue Carsonite Post 1' Northwest

S18°W 26.40' to set N & T in E side 10" White Pine

S60°E 25.35' to set N & T in N side 12" Sugar Maple

N45°E 22.25' to set N & T in W side 16" Sugar Maple

N52°W 52.15' to set N & T in SW side 18" White Pine

10 - Set 2" stamped Aluminum Cap on 5/8" x 34" rebar

Set Blue Carsonite Post 1' North

N63°W 28.21' to set N & T in N side 8" Cedar

N25°E 10.09' to set N & T in E side twin 10" Red Maple

N88°E 6.97' to set N & T in S side 10" Red Maple

S20°W 13.38' to set N & T in E side 4" Fir

Signed by:

Craig W. McVean

Date:

5/20/2004

Surveyor's Michigan License No.:

39088