

MAY 16 1997

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in COMMISSION

MONTMORENCY
(County)

Located In:
ALBERT TWP.

Corner Code #

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

11-06-1996 11:06:25

A. PANGAN-MCELROY
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey T 29N R 1E C-1
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

I, FREDERICK J. KING, in a field survey on May 29, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-1 - CORNER COMMON TO SECTIONS 5 & 6

May 1839 - Original Post set by Clason, Dep Sur. - Intersected 142 lks E of C-13
S40°E - 18 lks (11.88') - 5" Spr. Pine
S47°W - 30 lks (19.80') - 9" Spr. Pine

Date ? - F.N. Smith #754 - Don Marlatt, P.S. #18660 provided map of area, indicating that Smith had worked in area and Peer Committee felt that he had set this corner.

No Act 74 found Recorded for this Corner
No Act 132 found Recorded for this Corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-1 - CORNER COMMON TO SECTIONS 5 & 6

No Original Government Corner Evidence Found (T30N-R1E)
Found Axle Shaft @ Corner C-1 West - 93.40' - Found Conc. Mon @ Corner C-13 -
N45°E - 7.5' - Found Spk NW side of 8" J. Pine (OGN-93.72' - 142 lks)
S80°E - 4.1' - Found Spk N. side of 8" J. Pine
South - 11.55' - Found Spk W. side of 10" J. Pine
N80°W - 26.75' - Found Spk S. side of 18" R. Pine

This Corner Approved by County Peer Review on June 7, 1996, as the best available evidence of the position of the Original Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-1 - CORNER COMMON TO SECTIONS 5 & 6

Placed Montmorency County Re-Mon Cap on found Axle Shaft
N45°E - 7.49' - Set S&T above found Spk - NW side of 8" J. Pine
S80°E - 4.06' - Set S&T above found Spk - N side of 8" J. Pine
South - 11.52' - Set S&T above found Spk - W side of 10" J. Pine
N80°W - 26.54' - Set S&T above found Spk - S side of 18" R. Pine
Corner is 193' E of C.L. of N-S Gravel Rd. (Mathews Rd.)
West - 93.40' - Corner C-13 (30-1)



APPROVED BY
PEER GROUP

Signed by

Frederick J. King

Date October 24, 1996

Surveyor's Michigan License No.

25852

11/07/96

L.S.B.