

FEB 06 1998

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in **SECTION**

Montmorency
(County)

Located In:
Albert Township

Corner Code **#**

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

10-17-1997 11:39:55

A. PANGAN-MCELROY
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey T 29N R 1E K-4
- T R
- T R
- T R
2. Property Controlling S T R
- in Section S T R
3. Miscellaneous S T R
- Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

I, Larry G. Beauregard, in a field survey on June 5, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-4 $\frac{1}{4}$ corner for Sections 11 & 12.

Aug. 1840- Lewis Clason D.S., Set Qr. Sec. post. Wit's mkd: (Y.Pine 8" S 31° E 22 lks.) (Y.Pine 8" N 16° W 10 lks.).

June 1931- Frank N. Smith RLS #754, Fnd. $\frac{1}{4}$ post & stp. to SE but no marks, has been cut close to ground. No wit's mkd. Frank may have set mon. fnd. by Marlatt.

Feb. & May 1983- Donald E. Marlatt P.S. #18660, Fnd. Mon. in Fe. Cor. Two Cert. of Sur. One Rec. L. 3, P. 294. Wit's mkd: (S 70° E 6" Maple 15.8') (S 25° W 8" Maple 38.5') (S 85° W 6" Maple 31.4'). (Also July 1986)

Oct. 1985- Larry G. Beauregard P.S. #18654, Fnd. Mon. & wit's. Prepared Cert. of Sur. Not Rec. No new wit's mkd.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fnd. conc. mon. & Rec. wit's by Don Marlatt. DNR post & tab along side.

It isn't known who set monument originally.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-4 corner for Sections 11 & 12.

4" dia. x 36" conc. mon. Accepted as a perpetuation of the original government corner. Approved by the Peer Group on June 20, 1997.

S 18° W 38.5' R. Maple (R) & (M)

S 70° E 16.0' 6" Maple clump of 3.

S 85° W 31.4' 7" Maple. (R) & (M)

N 45° E 31.25' 7" Oak NBT.

Placed 60d penny spike, P.S. tag #18654 & blaze. (typ)

APPROVED BY
PEER GROUP

JUN 20 97

L.G.B.



Signed by Larry G. Beauregard

Date 10/17/97

Surveyor's Michigan License No. 18654