

Montmorency County Remonumentation

Liber 18 Page 08

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Montmorency
(County)

Located in:

Corner Code ##

1. Public Land Survey

T 29N R 3E

T 29N R 3E

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

**APPROVED BY
PEER GROUP**

NOV 0 5 93

08140

A. PANCAN-MCELROY

DEC 20 10 12 AM '93

RECEIVED
MONTMORENCY CITY
RECORDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	13		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Donald E. Marlatt, in a field survey on December 10, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-2) W. $\frac{1}{4}$ Cor. Sec. 6, T29N, R3E
Post set by Lewis Clason 1839.
Y. Pine 24-S 62 W-26
Y. Pine 28-N 45 W-97
Survey by D.E. Marlatt 11-5-1976.
Act 74 D.E. Marlatt L. 1, P. 215.

(A-3) S.W. Cor. Sec. 6, T29N, R3E
Post set by Lewis Clason 1839.
Y. Pine 18-S 14 W-26
Y. Pine 20-N 68 W-30
Y. Pine 25-N 16 E-30
Y. Pine 15-S 51 E-35
M.S.H.D. field notes 1956.
Survey by D.E. Marlatt 11-5-1976.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-2) W. $\frac{1}{4}$ Cor. Sec. 6, T29N, R3E
Fnd. $\frac{1}{2}$ " rod & cap #18660.
N 30° E 10.7' 20" Pine stp.
S 30° E 16.85' 12" Pine stp.
S 30° W 72.1' 12" Oak

(A-3) S.W. Cor. Sec. 6, T29N, R3E
Fnd. conc. Mon.
N 50° W 67.8' Pine stp. NBT
S 55° E 33.1' 24" J. Pine NBT
N 30° E 8.8' 5" J. Pine

No evidence of original corner.

No evidence of original corner.

The Peer Group approved (A-2) as a careful and faithful establishment of the position
of the corner.

The Peer Group approved (A-3) as the best available evidence of the position of the
original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-2) W. $\frac{1}{4}$ Cor. Sec. 6, T29N, R3E
Set conc. Mon. & Re-Mon cap.
N 45° E Pine stp. 10.82'
S 32° E Pine stp. 16.91'
S 14° W 4" Maple 23.20'
N 25° W 6" W. Pine 37.7'

(A-3) S.W. Cor. Sec. 6, T29N, R3E
Left conc. Mon. & Placed Re-Mon cap.
S 7° E 12" J. Pine 17.39'
S 40° E 26" J. Pine 32.9' NBT
S 60° E 11" J. Pine 30.37'
N 25° E 12" J. Pine 8.98'

Witnesses marked with 30 penny spikes & I.D. tags #18660.

Signed by Donald E. Marlatt

Date Dec 15, 1993

Surveyor's Michigan License No. 18660

