

FEB 08 2000

Liber 00012 Page 0387

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY  
(County)

Located In: BRILEY

Corner Code #

1. Public Land Survey

T 30N R 2E 1-8

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

STATE OF MICHIGAN  
MONTMORENCY COUNTY  
Recorded & Filed

11-24-1999 16:06:09

TERESA WALKER  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, FREDERICK J. KING, in a field survey on JULY 1, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1-8 - 1/4 CORNER COMMON TO SECTIONS 22 & 23

June 1840 - Lewis Clason, D.S. - Set Orig Post - N46°E-17 lks(11.22') 5" Spruce \* S71°W-13 lks (8.58') 4" Spruce  
July 1972 - Porters Survey Witness Records - Boat Spk In Rd. CL (1)WEST-33.67'-1" Pipe (2)EAST-33.00'-4" Conc Mon  
(3)N30°W-39.08'-14" J. Pine (4)N25°E-45.45'-13" Oak (5)S40°W-45.25'-P. Pole  
Aug. 1972 - D.E. Porter, PS#15410 - Act 74 - Boat Spk In CL & In Line Fnc to E. - Same Wit as July 1972 - Rec. L.1, Pg.5  
May 1974 - L.G. Beauregard, PS#18654 - Act 132 - No Cor Desc. - No Witness - Rec. L.1, Pg. 536  
Sept 1983 - D.E. Marlatt, PS#18660 - Act 132 - Fnd Boat Spk - Fnd Wit #1, #3, & #4 - Not Recorded  
Nov. 1996 - D.E. Marlatt, PS#18660 - Act 132 - Fnd Boat Spk (6)N60°W-31.65'-10" Oak (7)N45°E-69.20'-12" Oak  
(8)S08°E-42.6'-6" J. Pine (9)S67°E-42.4'-9" J. Pine - Rec. L. 10004, Pg. 440

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1-8 - 1/4 CORNER COMMON TO SECTIONS 22 & 23

Fnd Boat Spk In CL N-S Rd. (Ryan Rd)  
Fnd Witness #1, #3, #5, #6 & #7

APPROVED BY  
PEER GROUP

JUL 20 99

*J.L.B.*

This Corner was Approved by Montmorency County Peer Review on July 20, 1999, as the best available evidence of the position of the Original Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1-8 - 1/4 CORNER COMMON TO SECTIONS 22 & 23

N 35°E - 78.55' - Set S&T on SE side of 15" Oak  
N 45°E - 69.20' - Fnd Spk - 12" Oak  
EAST - 32.92' (R-33.00') - Fnd Conc. Mon.  
S 80°E - (RS08°E) - 42.14' (R-42.6') - Set S&T on N side of 6" J. Pine.  
S 50°E - 65.85' - Set S&T on SW side of 12" J. Pine  
S 50°W - (R-S40°W) - 45.25' - Set S&T on NW side of P. Pole  
WEST - 33.03' - (R-33.67') - Fnd l&C #18660 & 1" Pipe  
N 60°W - 31.15' (R-31.65') - 10" Oak (Now Stump)  
N 35°W - (R-N30°E) - 38.86' - (R-39.08') - Set S&T on NE side of 20" J. Pine  
Corner Is in C.L. E-W Gravel Rd. (Ryan Rd.)

Signed by *Frederick J. King*

Date October 18, 1999

Surveyor's Michigan License No. 25852

