

FEB 08 2000

Montmorency County Remonumentation

Liber 00012 Page 0373

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY (County)	Located In:	Corner Code #
BRILEY TWP.	30N R 2E	K - 3
1. Public Land Survey	T R	
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

11-12-1999 09:25:54

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, DONALD E MARLATT, in a field survey on JULY, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	P
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-3 CORNER COMMON TO SEC.S 1-2-11 & 12.
GLO COR. SET BY LEWIS CLASON APRIL 1840. Y. PINE 4" N67°E 8 L., ASPEN 5" S32°W 11 L.
F. SMITH PS#754 NOTES. NO DATE. NBT J.PINE 6" S78°W 26.7', NBT OAK 8" N36°E 17.1'.
COUNTY RD. COMM. NOTES(1941) MONUMENT CORNER. S45°W 50' CONC. MON., N45°E 50' CONC. MON.
N.C.CALDWELL PS#12018 ACT 132 DATED 10-20-71. FOUND MONUMENT. NO WITNESS. NOT RECORDED.
D.E.MARLATT PS#18660 ACT 132 DATED 10-10-75. L. 2, P. 129. FOUND MONUMENT. NO WITNESS.
D.E. MARLATT ACT 132 DATED 6-6-87 FOUND CONC. MONUMENT. NO WITNESS. NOT RECORDED.
L. BEAUREGARD PS# 18654 ACT 132 DATED 11-25-98. L. 10005, P. 62. FD. CONC. MONUMENT. N40°W 22.65' 8"OAK NBT, S45°E 26.1' 5"W.OAK, WEST 23.45' 4"W.PINE, S60°W 22.72' 8"R.OAK.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K - 3 CORNER COMMON TO SEC.S 1-2-11 & 12.
FOUND CONC. MONUMENT.

N40°W 22.65' 8"OAK NBT R.
S45°E 26.10' 5"W. OAK R.
WEST 23.45' 4"W. PINE R.
S60°W 22.72' 8"R. OAK R.

APPROVED BY
PEER GROUP

JUL 20 99

L.E.B.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-3 CORNER COMMON TO SEC.S 1-2-11 & 12.
PLACED REMON. CAP ON EXISTING MONUMENT.

N45°E 13"OAK 16.45'
N30°W 9"OAK 22.64'
S17°W 8"OAK 22.65'
S26°E 7"OAK 26.05'

WITNESSES MARKED WITH 40 PENNY SPIKES AND PS TAGS#18660.

APPROVED BY PEER GROUP JULY 20, 1999 AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

Signed by Donald E Marlatt
Surveyor's Michigan License No. 18660

Date 11-8-99