APR 2 4 1995

Surveyor's Michigan License No.

LAND CORNER RECORDATION CERTIFICATE

For corners in COMMIS	SSION Filing Requirement of	Act 74, Mich. P.A. 1970	STATE OF MICHIGAN MONTMORENCY COUNTY	
Montmorency (County)	Located In:Vienna Twp Corne	er Code ##	Recorded & Filed	15 -
Public Land Survey	T R	A-10)	11-02-1994 15:46:18 A. PANGAN-MCELROY	
Property Controlling	T R APPRO T R PEER (GROUP	REGISTER OF DEEDS	
in Section 3. Miscellaneous Property in Sec.	S T R	3 94 Reg	gister of Deeds Stamp & File Number	•
·			Service of the servic	
4. Lot No, H	ecorded Plat		A B C D E F G H I J K	
			2 6 5 7 4 3 7 2 7	- -
			3 4 7 8 9 10 11	_ _12
Larry G. Beauregard	in a field survey onMarch	, 19 <u>94</u> ,	5	1
do hereby certify that under requ	uirements of P.A. 74, Michigan P.A. of 1970, the conformance with regulations and rules there	corner points mentioned	6 18 17 16 15 14	_ 3-
current manual of survey instru	ctions of the United States Department of the	interior, Bureau of Land 🔍	7	+
above were in conformance with	Court of Law and/or that the corner points men the rules of the Michigan Board of Land Surve	eyors or by a Dècree of a	8 19 20 21 22 23	24
Court of Law; established, re expressed below:	e-established, monumented, re-monumented	, recovered, found as	10 30 29 28 27 26	25
•	rners, all in the same town and range, m	nay be recorded	11	+
on this certificate.			12 31 32 33 34 35	36
Description of original n	nonument and accessories and/or subsec	augnt restoration:	13	
	t set by John Mullett May 4,		•	
	0" N.37° E 20 links	Tamarack 10"	S 11° W 14 links	
156' West of 1 33 links). Re G.F. DeLaMater wits.: (Cedar Recorded in Of Peter E. Chens Cedar N 86° E L. 237, P. 409	r P.S. #693 (Otsego Co. Survey road. Wits. marked: (Cedar recorded in Otsego Co. Survey P.S. #693 (Otsego Co. Survey P.S. #693 (Otsego Co. Survey Respo Co. Survey records. tsego Co. Survey records. ard P.S. #14200 in 1977 fnd. 15.761) (4". Hemlock N 88°, E 65-406, Otsego Co. Records.	stp. 10" N 77° W 1 records. yor' in 1941 fnd. S 19° W 18.2') (C	9 links) (Cedar stp. 10" N or set 12" x 48" bar & mark ledar 12" N 22° W 21:7'). LaMater & marked wits.: (8 19° W 18.46'). Survey Rec	69 ed 8″ cor
B. Description of corner:	corner evidence found and/or i	method applied in	restoring or reestablishing	g
Fnd. 4' high Replaced ½" bar	bar in swamp 106.5'± West of Cedar post along side bar & with a 4" x 36" concrete monument and ty Remonumentation corner.	wits by DeLaMater	& Chenard.	
	• .			
			<u></u> .	
C Description of manumer	nt for corner and accessories established	I to perpetuate locating th	ne position of the corner:	* 11
A-10) \(\frac{3}{4} \) \(\text{Cor. Comm. } \frac{1}{4} \) \(\text{X } \) 36" \(\text{conc. mon. } \frac{8}{4} \)	to Sec's 25 & 30, T31N, R1E & Re-Mon. cap #18654. Acceptorner. Approved by the Peer Group or	T31N, R1W. ed as the best avail		men
N 89° E 15.8 S 22° W 18.1	8' 8" Cedar (R) NBT 18' 4" Cedar (R) NBT 55' 10" Cedar (R) NBT	s 10° E 31	.64' 5" Tw. Cedar 2.00' 10" Cedar stp. (old 1	иВп
Placed blaze, 20	penny spike & P.S. tag #19654 (typ)		A STATE OF MICH	S. C.
	. 4		BEAUREGAR	3