

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
NONTHORENCY

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 32N R 3E

K-7, L-7

T R

M-7

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, CARL KIISKILA, in a field survey on JUNE 25, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K-7

L-7

M-7

(NO EVIDENCE OF G.L.O. CORNER, B.T.'S, LINE TREES & TOPOGRAPHY, AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B" BELOW.)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-7

L-7

M-7

FD 1 1/4" PIPE FOR NW COR S-24 THAT FITS ONE US B.T. STUMP TO ME.

SET STD DNR MON AT REESTABLISHED N1/4 COR POSITION OF S-24 ON LINE BETWEEN FD ME & NW COR'S OF SEC 24 AND RECORD US-GLO DIST(127') EAST OF STREAM. FD 1/2" IRON BY P.S. E.LEWIS, 027452, S29°53'E 16.32'.

FD AND ACCEPTED 1 1/4" PIPE FOR SE COR S-13, FD REMAINS OF OLD SD TOP CEDAR STAKE ON GROUND. D.PORTER FD 1 1/2" PIPE & 3"x 3" CEDAR STAKE AT THIS COR IN 1974, WE BELIEVE TO BE SAME IRON BUT COULD NOT VERIFY WITS.(PIPE WE FOUND IS 1 1/2" O.D.).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-7

L-7

M-7

SET DNR MON INSIDE FD 1 1/4" GALV. PIPE.
10" R.PINE N54°W 12.41'
12" W.PINE N45°E 21.25'
10" R.PINE S26°W 21.37'
3" BALSAM FIR S57°E 8.89'
124"W.PINE BT STP N74°E 7.2'

SET STD DNR MONUMENT.
14" CEDAR S64°W 15.70'
6" BALSAM FIR S60°E 24.30'
9" BALSAM FIR N41°E 41.56'
10" CEDAR N10°W 45.27'
124" CEDAR N87°W 58.4'

FD 1 1/4" PIPE & SET CEDAR POST W/LOC TAG.
14" SPRUCE N18°E 34.10'
12" MAPLE S55°E 30.40'
10" W.BIRCH S34°W 13.97'
6" SPRUCE N69°W 22.45'
SW COR S-18, T32N-R4E, SET DNR MON, IS S01°22'23"E, 306.43'

16LO CALL FOR A 24" W.PINE N70 E 11 LINKS.

124"CEDAR SCRIBED NOT BY UNKNOWN SURVEYOR.



Signed by Carl T. Kiiskila Date 2-27-97

Surveyor's Michigan License No. 33981