MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION



LAND CORNER RECORD

T. 32 N.R. 4 E

			Montmore	ncy count
DESCRIPTION OF CORNER	1/4 Corner co	mmon to Section	s 30-31	
CORNER MONUMENT	Set 1" pipe w	ith 4" aluminum	cap	
DATE HORUMENT PLACED A	ND WITHESSED	May 24, 1966		
WITHESSES TO CORNER	•••	-,-		
N		20" B. Oak	NTOM	h2.5°
3b	-	18" B. Oak	S76E	50.01
CINCLE COMMEN REGISTERS	AND			

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set while making a survey of Section 30. Set section corners at U.S. record distance from section corner west on town line. This point checks most of the calls of the U.S. Record for the W 1/2 mile and leaves the apparent shortage in the E 1/2 mile where it probably occurred. Unable to proportion entire shortage over mile and fit the calls of the U.S. notes. No definite evidence of U.S. stumps.

SURVEYOR'S SEAL

SIGNED Lewell Detling D
REGISTERER AND SURVEYOR #10068

DATE June 7, 1966