SUPPLEY & REMONUMENTATION

MAR 1 3 2000

NEWAYGO COUNTY REGISTER OF DEEDS

1999 Newaygo County Remonumentation Project NOA M. BROWN

APPARTIANT

LAND CORNER RECORDATION CERTIFICATEFFR 28 PM 1 89

SECTION	FILING REQUIREM	MENT of Act 74, Mich.	P.A. 1970	
For corners in Newaygo (County)	Located in:	Corner Code#	Linda YN.	Brown
Public Land Survey	T <u>11N</u> R <u>12W</u> T R T R T R	F-13	vol. 2	296
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR		egister of Deeds Stam	p & File Number
4. Lot No, Recor 5. Private Claims	ded Plat		1 A B C D E F 6 2 - 6 - 5 - 4 -	G H I J K L M
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curre Department of the Interior, Burel Law and/or that the corner poconformance with the rules of Decree of a Court of Law; estable recovered, found as expressed by	corners, all in the same tow	of 1970, the comer ulations and rules the United States ocree of a Court of 5 above were in urveyors or by a 1, re-monumented,	5 1 1 1 1 1 1 1 1 1	- 10 - 11 - 12 - - 15 - 14 - 13 - - 22 - 23 - 24 - - 27 - 26 - 25 - - 34 - 35 - 36 -
South One Quarter Corner,	Section 33, Grant Township, Ne	waygo County, Michigan.	13	
A. DESCRIPTION OF O	RIGINAL MONUMENT AND	ACCESSORIES AND/C	OR SUBSEQUENT RE	STORATION:
G.L.O. N. Brookfield 183 12" Maple N82°E 44 Links 18" Black Ash N29°W 36 Measured 518 Links (341 Quarter Corner, Section 3 Northeast Corner of Section	s (29.04')#1 Links (23.76')#2 .88') from the South One 33, T11N R12W to the	set this by holding the R12W, and the Sou line extending East u		orner of Section 5, T on 33, T11N R12W, ence line North and
Lylo C Charbard D I C 1	HEUS		the Northwest Corner	

Book 70, Page 42 June 5, 1930 Gas Pipe on South side of gravel Measured 2668 feet from the South One Quarter Corner to the Southeast Corner of Section 33.

10N for also and **2W** (#7). This is in a blacktop road in a swamp area with much fill in place. Removed 1/2" rod and cap and set a 4" X 20" Harrison cast iron monument marked "County Surveyor".

12" White Oak S55°W 74.18' #3 12" White Pine N60°W 99.04' #4 14" Maple N45°E 116.64' #5

Clump of 4 Basswood 16" Stump South 58.00' #6

OVER \$

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 4" Harrison cast iron monument marked "County Surveyor" in the centerline of the East and West bituminous road. The condition of the recorded witnesses are: #1 and #2 gone, #3 good condition, #4 and #5 gone, #6 found (16" Stump South 58' ± to center), #7 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 4" Harrison cast iron monument marked "County Surveyor" as a substantial marker for the quarter corner and is accepted as a careful and faithful reestablishment of the original corner.

18" White Oak S63°W 74.10' Set spike with tag #22439 in Northwesterly side of tree. #3 Northwest Corner, Section 4, T10N R12W, (4" diameter Harrison cast iron monument with Kent County brass cap) West 304.81' #7

6" Maple S11°E 40.88' Set spike with tag #22439 in West side of tree. 20" Maple N33°E 154.25' Set spike with tag #22439 in East side of tree.

Signed by Norman L. Ocks	Date August 16, 1999
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971

Approved by Peer Review Group on August 19, 1999 Norman L. Ochs, County Representative.

M.R.O.

Revised May 14, 1975 Revised Jan., 1983

A. Description (cont.)

Charles E. Fricke R.L.S. #21781
July 6, 1992 Recorded in Liber 354, Pages 3800 and 3801
12" Oak S55°W 74.18' #3
12" Pine N60°W 99.04' #4
14" Maple N45°E 116.64' #5
16" Stump South 58.00' #6

SURVEY & REMONUMENTATION

MAR 1 3 2000

SECTION